
GLOVE SIZE CHART



HOW TO MEASURE YOUR HAND

Measure the width of your hand from the base of your first finger across your knuckles.



A proper fit is extremely important. An uncomfortable fit causes hand fatigue and ultimately could lead to a potential workplace hazard.



