

Matthews PaintManager® Software Guide

Section Number	Pages
1. Hardware	6
2. Software Activation	9
3. Networking Basics	10
4. Advanced Scale Settings	13
5. Dashboard and Navigation	17
6. Settings	18
7. Color Search	37
8. Mix Management	42
9. Job Management & Job Costing	53
10. Custom Formulas	62
11. Sundries and Sundry Kits	65
12. Pricing & Pack Size for Job Costing	67
13. Basic Inventory for Ordering and Receiving	76
14. Reporting	83

Section 1: Hardware	6
Software Requirements for Matthews PaintManager [®] Software	6
Power and Battery Backup	6
Scales and Advanced Functionality	7
The Mettler Scale	7
Scale Barriers	7
Part Number Summary for Matthews PaintManager® hardware	8
Section 2: Software Activation	9
Web Activation	9
Section 3: Networking Basics	10
Internet Update General Information	10
Internet Update - Enabling	
Networking Basics	11
Server Installations	11
Client Installations	11
Wired Networks	11
Wireless Networks	11
Server Firewall Configuration for Client Connectivity	
Client Connectivity	
Section 4: Advanced Scale Settings	13
Eligible Scales	13
Adding a New Scale	13
Adding a Scale Using Auto Detect	13
Adding a Scale Manually	14
Configure Advanced Settings	15
Section 5: Dashboard and Navigation	17
The Dashboard	17
Section 6: Settings	18
Shop Information	18
Application Settings Main Screen	19
Mixing Tab	20
Pricing	21
Jobs	22
Environmental Regulations (VOC)	23
My Settings	24

Internet Update General Information	25
Internet Update—Enabling	25
Internet Update Configuration	26
Backup and Restore	
Display Settings	
Scale Settings	
Print Settings	
Units of Measure	
Paint Line Settings	
Ready for Use Preferences	
Toner Management	32
User Management Main Screen	
Add a New User	
User Preset Descriptions	
Team Management Main Screen	
Creating a New Team	
Report Settings	
Language Settings	
Section 7: Color Search	
Section 7: Color Search Full Search Results	37 38
Section 7: Color Search Full Search Results Revision Results	
Section 7: Color Search Full Search Results Revision Results Compare Formulas	
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing	
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details	37 3838394041
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details Section 8: Mix Management	37 38 38 39 40 41 42
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details Section 8: Mix Management Mix Session	37 38 38 39 40 41 41 42
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details Section 8: Mix Management Mix Session Job Association.	37 38 38 39 40 41 41 42 42 42
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details Section 8: Mix Management Mix Session Job Association. Adding a Job.	37 38 38 39 40 41 41 42 42 42 42 43
Section 7: Color Search	37 38 38 39 40 41 41 42 42 42 42 42 43
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details Section 8: Mix Management Mix Session Job Association. Adding a Job. Weigh on the Scale. Mix Summary.	37 38 38 39 40 41 41 42 42 42 42 42 42 43 43
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details Section 8: Mix Management Mix Session Job Association Adding a Job Weigh on the Scale Mix Summary Split Mix	37 38 38 39 40 41 41 42 42 42 42 42 42 43 43 43 43
Section 7: Color Search Full Search Results Revision Results Compare Formulas Formula and Mixing Formula Details Section 8: Mix Management Mix Session Job Association Adding a Job Weigh on the Scale Mix Summary Split Mix Mix Queue Active Tab	37 38 38 39 40 41 41 42 42 42 42 42 42 43 43 43 43 43 43 43 45 46 48
Section 7: Color Search	37 38 38 39 40 41 41 42 42 42 42 42 42 42 42 43 43 43 43 43 43 44 44 44 44 44 44 44
Section 7: Color Search	37 38 38 39 40 40 41 42 42 42 42 42 42 42 42 42 42 43 43 43 43 43 45 45 46 48 49 50

Adding a Mix from the Pre-Mixed Inventory Screen	52
Adding a Mix from the Formula Details Screen	52
Section 9: Job Management	53
Jobs Main Screen Tile View – Active or Open Jobs	53
Job Main Screen – Job History or Closed Jobs	53
Add a New Job	54
Job Layer Tab	54
Job Layer Tools Menu Options	55
Sundries Tab	55
Contact Tab	56
Notes Tab	.56
Job (\$) Financial Tab	57
Run Invoice Options	58
Sign Order Options	.59
Transaction History Tab	60
Ready for Use Selections from the Dashboard or Main Menu	60
Selecting Undercoats and Clearcoats	61
Section 10: Custom Formulas	62
Custom Formula Main Screen	62
Creating a New Custom Formula	62
From an Existing Custom Formula	63
From Scratch	63
Custom Formula Edit - Components Tab	64
Details Tab	64
Section 11: Sundries and Sundry Kits	65
Enable a MPC Product for Sundry Use:	65
Create a non-Matthews Sundry:	66
Create a Sundry Kit:	68
Cloning a Kit	.69
Adding Sundries to a Job	.70
Section 12: Pricing and Pack Size for Job	71
Inventory and Pricing Main Screen	71
Manage Pricing	72
Pricing Screen	72

Moully Pack Size for Accurate Pricing	74
Manage Levels Screen	74
Select Container (Pack) Size	75
Section 13: Basic Inventory for Ordering and Receiving	76
Introduction	76
Benefits	76
Challenges	76
Inventory and Pricing Main Screen	77
Managing Product Levels	78
Tips for Managing Inventory List	79
Managing Orders	79
Creating a New Order	80
Add Items to the Order	80
Add items from Suggested Minimums	81
Add items from Inventory	81
	01
Add Items from Sundries	81
Add Items from Sundries Submit Orders	81
Add Items from Sundries Submit Orders Receive Orders	81
Add Items from Sundries	
Add Items from Sundries	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports The Reporting Main Screen	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports The Reporting Main Screen My Reports Tab	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports The Reporting Main Screen My Reports Tab Summary Reports Tab	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports The Reporting Main Screen My Reports Tab Summary Reports Tab Report History Tab	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports The Reporting Main Screen My Reports Tab Summary Reports Tab Report History Tab Creating a New Report Template:	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports The Reporting Main Screen My Reports Tab Summary Reports Tab Report History Tab Creating a New Report Template: Select Report Category and Report	
Add Items from Sundries Submit Orders Receive Orders Section 14: Reporting Program Access Settings for Reports: User Access Settings for Reports The Reporting Main Screen My Reports Tab Summary Reports Tab Report History Tab Creating a New Report Template: Select Report Category and Report Select Time and Scheduling Options	
Add Items from Sundries Submit Orders	

Section 1: Hardware

Software Requirements for Matthews PaintManager[®] Software:

- Windows[®] 7 Professional Operating System or higher
- Internet Explorer Version 9 or higher
- Windows Updates Enabled and Up-To-Date



Provide Safe Power with a Battery Backup (UPS)

- A UPS can save valuable equipment. If it quits working early in the two to three year life span it is probably because it did its job and handled a significant power event. Please replace it or look for potential environmental power conditions that may need to be addressed.
- Plugging your devices into the proper outlet is important. Please see the diagram below:



Scales and Advanced Functionality

The Mettler BBA242x scales bring a new level of comfort and functionality into the shop.

Full graphic display

The backlit LCD display with graphic capability allows full text and multi-language communication and guides you through your paint mixes with ease.

Safe to use

The BBA242 meets all pertinent international hazardous area standards to ensure your safety. **Unlimited connectivity**

With RS232, USB and WLAN connection, the BBA242x scales integrate into any IT environment.

The Mettler BBA242x Scale:

An easy interface allows you to download up to 20 recipes from a PC. The graphic display of the BBA242x form guides you through the mixing process and stores the mixing protocol inside the scale. Automated correction modes can be accessed in case you add too much of a component. The BBA242x paint offers all the features of the BBA242x form except the formula mode, making it a perfect solution for PC based mixing control.



Scale Barriers:

Non-compliant scale barriers must be used outside the mixing room and cables can be passed through the mixing room wall using the additional port on the conduit wall plate. Compliant barriers can be used inside the mixing room eliminating the need to run the data cable from outside the mixing room.



Part Number Summary for Matthews PaintManager[®] Hardware:

METTLER Toledo Item Number	Description	PART NUMBER	
	Stand Alone Complete Scale		
30026055	BBA242x Complete scale with EX1P Barrier	PPG838/EA	
	All-in-one Arrow Computer in the Mix Room		
30104576	BBA242x Scale Base-Only with EX1P Barrier and USB to RS232 Cable	PPG839B/EA	
30566154	BBA242x Complete scale with EX1P Barrier and USB to RS232 Cable	PPG840D/EA	
	Dell Computer outside the Mix Room		
30548968	BBA242x Scale Base-Only with APS242x USB Barrier	PPG841B/EA	
30404874	BBA242x Complete Scale with APS242x USB Barrier	PPG842D/EA	
	Division 1 Solution		
72235793	BBA242x Scale Base-Only without Power Barrier	PPG843B/EA	
30124267	124267 ADI856 Div1 touchscreen (with barrier & cables)		
30026057 BBA242x Complete scale without Power Barrier PPC		PPG844D/EA	
	5 - Gallon Solution		
30566498	Combi Bench Scale ICS426xd-AB30 w/APS768x Barrier	PPG848G/EA	
	Other Accessories / Components		
METTLER Toledo Item	Description	PART NUMBER	
72262434	Scale Base Protective Pan Cover (box of 5)	PPG845/PK	
71153871	Scale Display Protective Head Cover (box of 5)	PPG846/PK	
72262555	Complete Scale Stand (Column & Display only - no base)	PPG837/EA	
30431241	USB Power and Communication Barrier Box FM Div 1	PPG847/EA	
64088427	CABLE, USB TO RS232 CONVERTER, FTDI PPG836/E		

Section 2: Software Activation

Web Activation:

With an internet connection all you need is the customer's CTS number and zip code to Activate.

Software Activation	
CTS ID # 12345 Postal Code 12345 Manual Activation Activate	

Section 3: Networking Basics

Internet Update General Information:

- Internet Update now resides inside the *Matthews PaintManager* software.
- Updates occur nightly with incremental formula data updates and program updates only as needed.
- Users will receive 5 one minute warnings before the program shuts down for an update.
 - •Network clients will receive a command from the server to shut down as well.
 - •Users will need to finish their work or save their progress.
 - •Usually set to run at night or weekends to prevent any work disruption.
 - Network clients do not download updates individually because they receive updates from the server.
 - •Network environments only require the server to download updates which are applied to clients.

•When the *Matthews PaintManager* software is started on a client, it will check for updates and install them if they are available.

•Users will see a message stating an update is in progress.

•

Internet Update - Enabling:

- Internet Update must be first enabled in the Settings Application Settings screen on the General Tab.
- Once enabled, It will display on the Settings Screen.



Networking Basics:

There is a separate Installation Guide that details out the steps for installing and networking *Matthews PaintManager* Software.

Server Installations:

- •The device designated as the server will require a complete installation which installs the server •components along with the program.
- •The Server application will receive the Internet Update and make it available to network clients.
- •This installation will require an Activation when installed.

Client Installations:

- •Designated network clients require a custom installation to deselect any server components.
- •Client installs do not require activation as they cannot operate without a connection to a server with an activation.
- Clients do not download Internet Updates because the Server passes updates to the Client.
 Network drive mapping or path information is not required. The client will automatically search the network for a valid *Matthews PaintManager* Server installation and request a connection.

Wired Networks:



The Help Desk and CSSS Team will not provide support for wireless networks. The customer will need to provide their own IT support for installing and maintaining these networks.

Server Firewall Configuration for Client Connectivity:

The Windows firewall must be configured to allow client connections. Detailed instructions are available in the Installation Guide for this step.

Pontrol Panel\All Control Panel Items\Windows Firewall\Allowed apps						-		×
← → ✓ ↑ 🔗 > Control Panel > All Control Panel Items > Windows Fi	rewall > A	llowed app	s	ڻ ~	Search	Control Par	nel	Q
Allow apps to communicate through Windo To add, change, or remove allowed apps and ports, click What are the risks of allowing an app to communicate?	ows Firev Change set	vall tings.		Chang	e setting	gs		
Allowed apps and features:								
Name	Domain	Private	Public	Group P	olicy	•		
MSN Weather			V	No				
Netlogon Service				No				
✓ Network Discovery		\checkmark		No				
☑ Paid Wi-Fi & Cellular		. 🗹 💊	~	No				
Performance Logs and Alerts				No	- 1			
PPG.PaintManager.Server.ServiceHost				No				
Proximity Sharing	\checkmark	✓	~	No				
Remote Assistance	\checkmark	✓		No				
Remote Desktop				No				
Remote Event Log Management				No				
Remote Event Monitor				No				
Remote Scheduled Tasks Management				No	`	-		
			Details	. Re	emove			
			AI	low anoth	er app			
						_		
			OK		Cancel			

Client Connectivity:

Once the client installation is complete and the program is started for the first time, you will be provided with connection options based on the server computer name or the server IP address.

- The Computer name connection is the recommended option for most cases.
- The IP address connection is only recommended for servers with a static IP address.

문 Serv	er Selection
Multiple available s	ervers were found, please select the one you wish to connect to.
desktop-0b9ul	F 192.168.1.78
	OK Cancel

Section 4: Advanced Scale Settings

Elligible Scales:



Add a Scale Using Auto Detect:

From the Dashboard select Settings then Scale Settings.



Page 13 of 91

Add Scale	
Auto Detect	Manual
Manufacturer Port Communication Sartorius COM10 Advanced 2 Mettler COM1 Basic Select Advanced Communication (Only available for Sartorius scales)	Auto Detection will scan the computer's COM ports for attached serial devices and attempt to discover compatible scales. Press the Auto Detect button to begin Auto Detect 3 Select Auto Detect
Refresh COM Ports	Close

Add Scale	
Results Scan complete bar. Auto Detect Check communication	Automatically checks Use Scale
COM10 Sartorius PMA7501-X00V1	Test Scale 🔽 Use Scale
Device Information Manufacturer: Sartorius Model: PMA7501-X00V1 Serial Number: 0032610176 f 0.0 part Maximum Weight: 8473.7 part Weight: Parts Current scale UOM setting	Firmware: 002333 Minimum Weight:
Cancel Select to add	detected scale Add Selected
	Close

Note: A scale previously installed with <u>basic</u> drivers may have to be removed and re-added with <u>ad-</u><u>vanced</u> drivers after a computer reboot.

Adding a Scale Manually:

If you cannot connect to a scale using the auto detect method it is recommended you contact the Help Desk.

Configure Advanced Settings:

Scale Settings	Save Cancel
Scale Settings	Sartorius PMA7501-X00V1
Virtual Scale	Default 1
Virtual Scale	✓ Negative Tare 2
Sartorius PMA7501-X00V1 9 😣	Scale Notify if Can Removed 3
	Read Scale Keypress 4
	Lock Screen* 5
	Lock Keys* 6
	*Modify from Scale Test screen
	Decimal Precision: 1 Scale information
	Minimum Weight: 0 part
	Model: PMA7501-X00V1
	Firmware: 002333
	Serial Number: 0034209808
	Driver: Sartorius BPI (Advanced)
	Port: COM1 (Current com port selection)
+ Scale	T Scale Test Edit 8

1. Default:

Sets the selected scale to be the default for weighing.

Scale selection can be changed prior to weighing.

- 2. Negative Tare: Scale measures from a negative starting value to zero in sync with the software display.
- **3.** Scale Notify if Can Removed: Scale display flashes a warning when the container is removed from the scale before mixing steps are completed.
- 4. Read Scale Keypress: This feature is only usable in the Scale Test screen. (See step 7 below)
- 5. Lock Screen:

Blanks the scale display requiring the user to follow the readout on the touchscreen. Recommended for job cost environments to encourage capturing all mixing on the scale. This must be configured using the Scale Test button at the bottom of the screen.

6. Lock Keys:

Use with Caution, disables access to the scale setup menu.

Disables the "Enter", "C", and "Up/Down" keys used to change the scale configuration.

Power, Toggle, and Tare buttons are still active.

When this feature is enabled the scale is locked and the only way to unlock it is with a connection to a Matthews PaintManager[®] software installation.

This must be configured using the Scale Test button at the bottom of the screen.

7. Scale Test: Used to setup advanced functions and test scale features. When selected you may have to choose options to close the scale server software first to gain access to this screen.

8. Edit: Used to make manual changes to scale communication parameters.

•Required to change scale com port selection.

•Recommend not altering other settings without guidance from the Help Desk.

•Unit of measure settings on this screen do not change settings in the scale. The scale must be configured for UOM using the setup on the scale.

9. Remove: To remove an unused scale or to re-add a scale.

Selected Scale:	Sartorius PMA7501-X00V1	Change com por	t here
Driver	Sartorius BPI (Advanced) 🔻	Parity	None 🔻
Port	сом1 🗸 🗸	Stop Bit	None 🔻
Baud Rate	•	Handshake	None 🔻
Data Bit	•	Decimal Precision	1 🔹
Manufacturer	Sartorius 🔹	Serial Number	0034209808
Model	PMA7501-X00V1	Firmware	002333
Minimum Weig	ht - 0.0001 + Gran	ns 🔻 Not used	
Maximum Weig	nht - 7,513.8107 +	Grams 🔻 Not use	d
Weight Parts	▼ Not used		
Cancel			Save

Section 5: Dashboard and Navigation



The Dashboard:

1. Dashboard Tiles:

Single step navigation to enabled program components from the Dashboard

2. Main Menu:

Two-step navigation to enabled program compo-

nents from anywhere in the program

- 3. Software Version
- 4. Logged in User
- 5. Logout
- 6. Question Mark 🕜

Legal Notices

About (i.e. program, customer, and computer Information)

7. Windows Controls



Section 6: Settings



Shop Information:

Shop Information			Save	Cancel	
Shop Name	CTS ID #				
PPG Industries		455811			
• Address					
19699 Progress Drive	Address Line 2		Address Line 3		
Postal Code	City		State/Province		
44149	Strongsville		ОН		
Additional Info					
Subscription type: Matthews PaintManager® Full In Site Category: MPC Price List: MPC Activation Expiration: 2/27/2021 Manually Update Activation	ternet				

Application Settings Main Screen:

$\equiv \Leftrightarrow$ Matthew	vs PaintManager® Color Software Beta App: 18200225 / Data: 182003.16	Welcome, Sys Admin Logout 🔞 💻 🗂 🗙					
< Арр	lication Settings	Save Cancel					
General	 Record as Mixed Mixing and Weighing Pricing 	Auto Logoff (In Minutes) 120					
	✓ Inventory	Show custom formulas in color search					
Mixing	v Jobs	Color Search Display Default					
	✓ Team Management	Grid					
	Environmental Regulations	Default Vendor					
Pricing	RapidMatch™	Select Default Vendor					
	✔ RFU	Enable Physical Inventory for Liquid Products					
lebe	Custom Formulas	Automatically add reduction					
1002	Advanced Reporting						
	✓ User Management						
Environmental	✓ Internet Update						

Record as Mixed:

Places a "Record as Mixed" button on the Mix Session Tab to record mixes to a job without having to mix them across the scale.

Pricing:

Displays the "Inventory & Pricing" Tile on the Dashboard

Provides access to configure margins, discounts, and custom pricing

Shows pricing information for mixes on the "Mix Summary" and "Formula Details" screens

Enables the Pricing tab inside a selected Job for view financials and printing an Invoice

Provides a Tab on this screen to select options for how pricing is viewed in the program

Inventory:

Displays the "Inventory & Pricing" Tile on the Dashboard to allow the configuration of inventory selections, pack size, sundries, sundry kits, and access to ordering and receiving

Jobs:

Display Job tab on this screen to configure preferences

Displays the "Jobs" Tile on the Dashboard

Enables the Job Management Screen for mixing on Jobs for financial measurement

Team Management:

Provides a button on the "Settings" screen to allow access to setup and manage teams

Environmental Regulations:

Displays a Tab on this screen for configuring VOC tracking

<u>RapidMatch®</u>:

Displays the "RapidMatch®" Tile on the Dashboard

Provides access to the Readings List

Displays button on Settings screen to detect the spectrophotometer

RFU:

Displays a Tile on the Dashboard to allow access to configure and access RFU combinations. Provides access to the RFU favorites for Undercoats and Clearcoats on the "Formula and Mixing"

Custom Formulas:

Provides a Tile on the Dashboard to access this feature

Allows the creation of Custom Formulas on the "Formula Details" screen on the Tools Menu

Advanced Reporting:

Enables the "Report Settings" button on the "Settings" screen

User Management:

Enables the "User Management" button on the Settings screen

Internet Update:

Provides an "Internet Update" button on the Settings screen for configuration to allow scheduled updates

Mixing and Weighing:

Provides the "Scale Settings" button on the Settings screen to detect and configure scales Provides a "Mix" button on the "Mix Session" screen to weigh product on a scale

Auto Logoff:

Minutes of non-use before the program requires a user to log back in (480 max – 8 hrs)

Show custom formulas in color search:

Shows custom formulas in color search results that were created with the code being searched

Color Search Display Default:

Select Grid or List view for Color Search, Custom Formulas, and Jobs

Default Vendor:

Used if you are creating orders

Enable Physical Inventory for Liquid Products:

Enables inventory weigh capability (See Section 17 topic, "Weighing Inventory for Accurate Stock Levels and Valuation")

Default Segment:

Choose the segment you want to default to for color searches

Automatically add reduction:

If only one Ready for Use Preference exists for color mixes it will be automatically added to the color mix on the Formula Details Screen prior to mixing.

Mixing Tab:



1. Always Skip Customer Assignment:

- Allows a mix to be assigned to a customer when Jobs are not being used
- Only works if Jobs is not selected in Settings-Application Settings-General Tab
- When unchecked, selecting Mix or Record as Mixed the user is prompted to select a customer
- Selecting a customer is not required and can be skipped
- These mixes can be summarized by customer on the Customer Mix History report

2. Tint a Formula:

• Allows tinting of formulas

3. Enable Can Management:

• Provides ability to add can costs to jobs and have program suggest can size for mixes

4. Most Mixed Formula Minimum Count:

- Flags formulas during color lookup that have been mixed this many times
- Flagged mixes are moved to the front of the search results list

5. Reset Counts:

Resets all mix counts back to zero

6. Enforce Waste Reason:

• When checked requires a Waste Reason to be selected when a mix is wasted

7. Custom Waste Reasons:

• Optional custom waste reasons can be added here in addition to program defaults

8. Save

< App	lication Settings		3	Save	Cancel
General	Pricing Calculation Margin	.	1		
Mixing	Pricing Display Price Only	•	2		

Pricing:

- **1. Pricing Calculation**
 - Select Margin or Markup (Margin is the recommended default)
- 2. Pricing Display
 - Choose the way the program displays pricing (Both is recommended for job costing)
- 3. Save

Jobs:

< App	plication Settings	Save Cancel
General	✓ Require Jobs for Mixing	Automatically Close Jobs
	✓ Financials	Number of Days Until Jobs Close
Mixing	Expected Cost per Hour	- 180 +
	- +	Extend at the End of the Month
	Non-Sprayable % of Total	Track Rework
Pricing	Non-Spravable Line Item Description	Custom Rework Reason 1
Jobs	Default Job Sort Order	Custom Rework Reason 2
	Due Date Ascending	Custom Rework Reason 3
Environmental		

Require jobs for mixing:

- This is automatically selected and cannot be changed when Environmental Regulations is selected on the General Tab.
- When Environmental Regulation is not selected, this can be unchecked to make job selection optional when mixing that will place a "Skip" button on the job selection screen.

Financials:

- This is automatically selected and cannot be changed when "Environmental Regulations" is selected on the General Tab.
- This selection will enable the Financial "(\$)" tab on the individual job screen.
- This must be selected to print an Invoice.

Expected Cost per Hour:

- This value is used as the desired target in reporting to measure actual results to target.
- This value will be determined by market trends and current pricing.

Non-Sprayable % of Job Total:

 This value will be used on the Job Financial tab to determine what percentage of the Job Total cost/ price will be allocated for non-sprayables.

Example - If the "Non-Sprayable % of Job Total" is 30% and the Job Total is \$100:

- \$30 will be allocated to non-sprayables \$70 to sprayables
- Also determines what is printed on the invoice

Non Sprayable Line Item Description:

• This is the description that will print on the invoice for the non-sprayable calculation

Automatically Close Jobs:

Closes jobs automatically to help the Job screen from growing too large to manage

Number of Days Until Jobs Close:

The time period the jobs stays open from the date it was created before being closed.

This will vary depending on how long jobs generally stay in the shop.

Closed jobs will be available for viewing in the program even if they are closed.

Special permissions are needed by the user to be able to modify a closed job.

Extend at the End of the Month:

Recommend this be selected for job costing and/or VOC reporting.

This will keep report data together by the month when it makes a difference.

If the shop is using the Paint Shop Interface, the vast majority of the jobs will be closed before the auto close time period is reached so this setting is not as critical.

Track Rework:

Provides an option to flag/un-flag a layer/mix on a job as rework.

This button will be displayed on the job layer tab on the Tools menu for a given mix.

Custom Rework Reasons:

Can be added here to display in addition to the defaults provided.

Save

Environmental Regulations (VOC):



My Settings:

This feature allows the user to set preference items that are applied when they login.

1	Sys	Admin
2	Password	Confirm Password
	Canguage Use Shop Language ▼	5. Select a home page Start Page 5 Select Start Page 5
3	Use Shop Region 🗸	3. Select the Language and Region
4	Color Search Display Default Grid	differently depending on the region
	4. Select Grid or List display. This will be applied to the Color Search results, Custom Formulas screen, and Jobs screen.	
6	Save 6. For changes to take effect, you must first save your changes, log out, and	Cancel

Internet Update General Information:

•Internet Update now resides inside the Matthews PaintManager software.

•Updates occur nightly with incremental formula data updates and program updates only as needed.

•Users will receive 5 one minute warnings before the program shuts down for an update.

- Network clients will receive a command from the server to shut down as well.
- Users will need to finish their work or save their progress.
- Usually set to run at night or weekends to prevent any work disruption.
- Network clients do not download updates individually because they receive updates from the server.
- Network environments only require the server to download updates which are applied to clients.
- When the *Matthews PaintManager* software is started on a client it will check for updates and install them if they are available.
- •Users will see a message stating an update is in progress.

Internet Update - Enabling:

- •Internet Update must first be enabled in the Settings Application Settings screen on the General Tab.
- •Once enabled it will display on the Settings Screen.



Internet Update Configuration:

Internet Updat	te	4	Save	Cancel
✓ Enable automatic daily updates	1			Update Now
DAILY DOWNLOAD TIME 12:00 AM	• 2 a	DAILY INSTALLATION TIME	1:00 AM 🔻 🤇	5
Dowr	load and Installation time m	ust be at lease one ho	our appart	
Date/Time Status				
↓ ↓				
Update status information will	populate here as steps are	completed		
				6
Software Version	Data Version			Rofresh
Current Application Version, 0.8.1702.4,	Current Data version 0.6.1/02.1			Reiresn

1. Enable Automatic Daily Updates

2. Daily Download Time

•Recommended setting this outside business hours.

3. Daily Installation Time

•Must be at least one hour later than the daily download time.

•If your internet download speed is slow this should be increased.

4. Save

5. Update Now

•Will download updates and install them now.

Caution: This will shut down the server as well as all network clients.

6. Refresh

•Refreshes the update status.

•Use to check for possible errors encountered by the update.

Backup and Restore:

≡ 💠 Matthews PaintManager® Color	Software Beta App: 182003.34 / Data: 1.82004.40 Welcome, Sys Admin Logout 😢 💶 🗙
Backup and Rest	CORE 5 Save Cancel Default file name
Backup Now	PaintManager_20200421101704.pmbak
Set Backup Location	C:\ProgramDataPaintManager\Data Backup
1 Enable Automatic Database Backups	3 Number of months to retain backups - 3 + 4
Time Period Day Week Month	D PM ▼ Day of Week Su Mo Tu We Th OFr Sa
Database Backups	
PaintManager_20200403160000.pmbak PaintManager_20200417160000.pmbak PaintManager_20200410160000.pmbak	A backup can be selected from this list to Restore
PaintManager_20200327160000.pmbak	8 Select Restore 9

Backup:

- 1. Enable Automatic Backup: Check to enable
- 2. Time Period: Select desired time interval for automatic updates to be initiated
- 3. **Time:** Choose the desired time for the backup to take place. (Preferably outside normal business hours.)
- 4. Months to Retain Backups: Backups older that this selection will be deleted
- 5. Save: Save selected settings for them to take effect
- 6. Backup Now: Select to initiate an immediate backup

Restore:

7. Database Backups: A list of backups that can be selected to restore

"C:\Programdata\Matthews\PaintManager\Data Backup\"

- 8. Select: Choose a backup that is not in the default backup folder, such as a flash drive
- 9. Restore: Once a backup is selected this will initiate the restore process

PaintManager_20170213081208.pmbak							
Month Hour & &							
	Year	Day	Minute	Seconds			
PaintManager_	2017	<mark>021</mark> 3	0812	08	.pmbak		

Backup File Name Description:



Scale Settings:

Authews PaintManager® Color Software Beta App: 1.8.2003.34 /	' Data: 1.8.2003.37	Welcome, Sys Admin Logou	ıt ?		ZX
Scale Settings		Save		Cancel	
Scale Settings	Virtual Scale				
Virtual Scale	✓ Default				
	Negative Ta	re			
	Scale Notify	r if Can Removed			
	Read Scale	Keypress			
	Lock Screer	1*			
	Lock Keys*				
	*Modify from S	cale Test screen			
	Decimal Preci Minimum We Maximum We M Firm Serial Nur D	ision: 1 bight: 0 g bight: 100000 g odel: PPG Virtual Scale ware: 1 nber: 0123456789 river: Virtual Scale Port: VIRTUAL_COM Scale Test Edit			
+ Scale					

7 Print Settings:

The DYMO[®] label printer no longer needs to be configured in *Windows*. Label size, orientation, font and barcodes are all determined based on the Template selection in this setup screen.



1. Printer Selection:

Select the Windows printer for your label and Paper printer

2. Copies:

Choose the number of labels or paper copies to print by default

3. Show Print Dialog Box:

Recommended that this is **NOT** selected for most situations. When selected this will cause the *Windows* print dialog box to appear each time a document is printed. Not selecting this will prevent unnecessary steps in the printing process.

4. Show Print Preview:

Recommended that this option **BE** selected. This will allow for additional information to be placed on a printed label as well as previewing reports before printing.

5. Template selection (based on user preference):

30256 Landscape Full Formula is the label template preference for most users.

6. Save

Units of Measure:

🗮 🛟 Matthews PaintManager® Color Software Beta App: 1.8.2003.34 / 1	Data: 1.8.2003.59 🛛 Welcome, Sys Admin Logout 🕜 💻 🛅 🗙
 Units of Measure 	9 Save Cancel
Select to show formulas as either incremental or cumulative.	Density
Incremental 1	lbs/gal 2 🔻
Final Target	Components
Formula Target Unit Type	Component Unit Type
Volume 3	Weight 6 🗸
Default Unit	Default Unit
U.S. Fluid Ounces 4	Grams 7 🔻
Default Amount	# of Decimal Places
- 1 5 +	- 1 8 +

1. Select Incremental or Cumulative:

Incremental is the recommended default which will provide a target amount for each specific component of a formula.

2. Density:

lbs/gal is the recommended default.

Final Target

3. Formula Target Unit Type:

Volume is the recommended default which will allow the user to select the quantity to mix based on units such as fluid ounces, pints, or quarts.

4. Default Unit:

The unit selected here will become the default for mixing and can be changed before mixing. This will also be the Unit of Measure for creating new report templates.

5. Default Amount: This is the default quantity used for every product mix which can be changed before mixing.

Components

6. Component Unit Type:

Weight is the recommended default. This selection will allow the user to weigh the selected mix by weight such as parts or grams.

7. Default Unit:

Typically this will be either Parts or Grams depending on user preference. Note that for accurate weighing of products this setting must match the UOM set for the scale.

8. Decimal places:

1 is recommended

9. Save



¹⁰ Ready for Use Preferences:

≡ 💠	Matthews PaintN	∕lanager® Co	olor Software Beta App: 18.2002.25 / Data: 1.8.200	3.16	Welcome, Sys Admin Logout 👔 🔔		Х
<	Ready Fo	or Use	Preferences		Export	Imp	ort
		2	Favorites		1 Master List		
All Cate	egories 4	All Paint Line	es 🔻 All 👻 Product code searc	h	3		×
5	PRODUCT GROUP	SUBCATEGORY	APPLICATION				<u>^</u>
\odot	274528SP	PRIMER	Gray Epoxy Primer 2.1 VOC	1.	Master List—Shows all products available to		
$\overline{\mathbf{v}}$	274530SP	PRIMER	White Epoxy Primer 2.1 VOC		select for RFU		
\bigcirc	274531SP	PRIMER	Black Epoxy Primer 2.1 VOC	2.	Favorites List—Displays all products selected as favorites.		
\odot	274685SP	PRIMER	U-Prime White Urethane Primer 2.8 VOC	3.	Search—Search Master List and Favorites List		
\odot	274685SP	PRIMER	U-Prime White Urethane Primer 3.5 VOC		with specific product code or name.		
$\overline{\mathbf{v}}$	274777SP	PRIMER	Tie Bond Adhesive (Zero VOC)	4.	Filter Options—Filter results by paint line or		
\sim					category.		_
							\sim

Ready for Use Preferences (Continued):

≡ 💠 Matthews PaintManager® Color S	Welcome, Sys Admin Logout 👔 👝 📄 🕻	
Keady For Use Print	eferences	Export Import
Favo	brites	Master List
All Categories All Paint Lines	Product code search	8
A2228SP CLEAR	APPLICATION 2	
42228SP 43270SP 6379 3 1 1	I. Search for a product	t.
VOC Category:		
42228SP 43270SP 6396	SP 3 2. Select the desired R	FU combination.
VOC Category:	3. Select the star to high	ghlight as a Favorite.
42228SP 43270SP 4528	IOSP	
VOC Category:		
		\sim
	Software Beta App: 1.8.2002.25 / Data: 1.8.2003.16	Welcome, Sys Admin Logout 🕜 👝 🗇 🔪
Ready For Use Pr	references	Export Import
Fave	orites	Master List
All Categories All Paint Lines 	All Product code search	8
42228SP 43270SP 63	396SP MAP Sati	in Clear
Shop Notes:	Select the Favorites Tab to see that	the Favorite is 🛛 🗖 📷
VOC Category:	now available.	

11 Toner Management:

MA	NAGE LEVEL	.S All Paint Lines	All Categories 🔻	All Minimums 🔻	All Inventor	y 🔻	Product cod	e search	8
			Select A	All Clear Sele			Used	Save Ca	ancel
USED	CODE	DESCRIPTION	SKU	PACK SIZE	QTY	MIN	REORDER	ADD TO CART	\land
•	Binder								١.,
~	283320SP	SATIN VOC CATALYST	283320SP/04 🔻	1 Quarts	0.00	0.00	0.00		
~	283800SP	VOC MAP CATALYST	283800SP/04 🔻	1 Quarts	0.00	0.00	0.00		
~	43270SP	UNIVERSAL CATALYST	43270SP/04 🔻	1 Quarts	0.00	0.00	0.00		
~	43621SP	BRUSHING CATALYST	43270SP/04	1 Quarts	0.00	0.00	0.00		
~	43999SP	SLOW CATALYST	43270SP/01	1 Quarts	0.00	0.00	0.00		
~	6278SP	HIGH PERFORMANCE CATAL	6278SP/01	1 Gallons	0.00	0.00	0.00		
~	74735SP	ACTIVATOR	74735SP/01	1 Gallons	0.00	0.00	0.00		
~	74766SP	PT ACTIVATOR	74766SP/01	1 Gallons	0.00	0.00	0.00		
~	74781SP	HBEF ACTIVATOR	74781SP/01	1 Gallons	0.00	0.00	0.00		
~	MAP-LVX101	EPOXY HARDENER	MAP-LVX101/04	1 Quarts	0.00	0.00	0.00		
~	MAP-LVX270	MAP-LV CATALYST	MAP-LVX270/04 🔻	1 Quarts	0.00	0.00	0.00		

12 User Management Main Screen:



Add a New User:

🔲 💠 Mathews PaintManag	er # Color Software Bea App 1820225/Dea 18200	1	Weizene, Syr Admin Logout 🔞 🔔 🗇 🗙
1 User		JL Presets	
First Name 1	Last Name 2		Is Administrator?
Checkwood Diverse	Personal Control of Co	Formulas	
Der Name 3		Mix Formula	
Concession of Co		Manage Inventory	
Suggested User Names:		View Inventory	
		Volume Estimator Optional	
	4	Record as Mixed	
		Formula Tinting 10	
A Password		View Pricing	
5	5	Manage Pricing	
		Under / Over Pour Formula	
14 Language	Expiration Date	Manage RTS	
Linglish 6	Erter date 7	Custom Formula	\sim
United States	•		
			found
			Lance

- 1. First Name
- 2. Last Name

3. User Name:

Note User Name cannot be edited after it is saved as it will be used to reference all transactions for this user. Be mindful of what you enter in this field before you save.

4. Suggested User Names:

The system will recommend some options but other entries are accepted.

5. Password:

Must be minimum of 4 alphanumeric characters and entered twice for verification.

6. Language:

This language is specific to this user when logged in and overrides the shop language.

7. Expiration Date:

This is used for guest painters who may only need this login for a short time.

8. Preset:

Based on user Role; Manager, Painter, or Support

9. Is Administrator?:

This selection will grant the user access to all facets of the program regardless of the preset selected.

10. Adjust Presets:

Adjustments can be made to any Preset recommendation.

User Preset Descriptions:

Formulas	Features Available If Selected		
Mix Formula	Weigh formulas across the scale		
Manage Inventory	Create Sundries, Create Sundry Kits, adjust Pack size and Quantity		
View Inventory	View Inventory list but cannot make changes		
Record as Mixed	Provide Record as Mixed button on the Mix Session Tab		
Formula Tinting	Allow user to tint/adjust formulas		
View Pricing	View Pricing in the Inventory and Pricing screen		
Manage Pricing	Enter Discounts & Margins percentages, customize pricing		
Under / Over Pour Formula	Provides Skip Button on Weigh Screen - option to under/over pour		
Manage RTS	Can Edit, Create, Delete RTS Favorites		
Custom Formula			
Create / Edit Formulas	Create and Edit custom formulas		
Jobs			
Jobs Contributor	Allows mixing to a Job		
Jobs Management	Create, Close, Edit jobs and assign Teams & Users to a Job		
View Customer List	Create and Edit Contacts and Vendors		
Manage Teams	Create and Modify Teams		
Modify Closed Jobs	Edit, add mixes to closed Jobs		
Application Settings			
Manage Users & Settings	Ability to manage Users		
Software Updates	Access to Internet Update and ability to change settings		
Application Settings	Grants access to Settings – By default only Admins have this		
Reports			
Create Reports	Create new report Templates		
Run Reports	Run existing reports		
View Reports	View historical saved reports		

13 Team Management Main Screen:

Team Management is used to capture accurate financial measurements for environments where more than one technician mixes on the same Job. In this event the Team would be measured not the individual.

😑 💠 Matthews PaintManager® Color Software Beta App: 1.8.2003.34 / Data: 1.	8.2004.0 Welcome, Sy	vs Admin Logout	
K Team Management		Add a New Te	am + Team
TEAM			l
Team 1 List of Teams	Delete a Team	Delete	Edit
Team 2		Delete	Edit
		Ē	dit a Team

Creating a New Team:



14 Report Settings

≡ 4	Hatthews PaintManager® Color Software Beta App: 1.8.2003.34	/ Data: 1.8.2003.37 Welcome, Sys Admin Logout 🕐 🔔 🛄 🗙
<	Report Settings	Save Cancel
Sele	ect Reports	
~	Select All	Keep non-VOC Reports for
	~ -	365 O Days Vears
(💽 🗹 Gross Profit	Keep VOC Reports for
(🕑 🗹 Mix Audit	1,095 O Days Years
		Summary Reports
(Sign Order	
(Inventory	Enable Summary Reports
(💽 🗹 Cost	
(VOC & HAPS	
(🕑 🗹 Usage	
(Customer	

15 Language Settings:

🚍 🕂 Matthews PaintManager® Color Software Beta App: 1.8.2003.34 / Data: 1.8.2004.4	Welcome, Sys Admin Logout 🕜 💻 📉 🗙
K Language Settings	Save Cancel
1 anguage 2 Region	
English United States	•
Numbers Format	
Override Regional Defaults	
Currency Grouping Separator Decimal Symbol	

1. Language

This is the program level setting but users can select a different language which overrides this setting when they log in.

2. Region

The same language can vary by region, so by combining a language with a region the program will provide a more meaningful translation.

• *Example:* The French language spoken in France is different than the French language spoken in Canada.

3. Numbers Format

Customize the formatting option to your region.
Section 7: Color Search

	➢ Matthews PaintMan	ager® Color Software	Beta App: 1.8.2003.34 / Data: 1.8.2004.4	Welcome, Sys Admin Logout 📀 🗕 🗂 🗙
1	mp number, name, source	e, color family		2 🖉
	Settings	Contacts	Custom Formulas	
	My Settings	Ready For Use	Reporting	
	Jobs	■≣o Inventory & Pricing		

1. Enter Search Criteria

Searchable formula elements include color code, name, source (manufacturer), color family or any combination entering a space between each one.

•Wildcard searches using the % symbol for partial criteria searches.

%abc will return any records that end with 'abc'

abc% will return any records that **start with** 'abc' %abc% will return any records that **contain** 'abc' Wildcard searches include results for all eligible search criteria.

≡ 💠 Matt	thews PaintManager® C	Color Software Beta App: 1.8.2002.25 / Data: 1.8.2003	.16	Welcome, Sys Admin Logout) – 🗆 X
brilliant g	gold				3 🛇 ۶
	Paint Lines	Color Attributes	Color System ▼	SORT Relevance	
Showing 16	of 16 results COLOR CODE	DESCRIPTION	COLOR SYSTEM	CODE	
0 🛞	46400SP	BRILLIANT GOLD	MATTHEWS PAINT	MP101491	\sim
0	LVSFP400	BRILLIANT GOLD	MATTHEWS PAINT	MP101514	
0	18265	BRILLIANT GOLD (NON-MET.)	MATTHEWS PAINT	MP18265	
•	18645	BRILLIANT GOLD BASECOAT	MATTHEWS PAINT	MP18645	
•	28645	BRILLIANT GOLD BASECOAT	MATTHEWS PAINT	MP28645	
0	30133	BRILLIANT GOLD	MATTHEWS PAINT	MP30133	
0	37466	BRILLIANT PALE GOLD	MATTHEWS PAINT	MP37466	
0	46600	HI-HIDE BRILLIANT GOLD BASE	MATTHEWS PAINT	MP46600	
0	67171	BRILLIANT GOLD	MATTHEWS PAINT	MP67171	

2. Search

Initiates a full search with filter options and additional formula information.

3. Cancel

Clears all search criteria

Full Search Results:

🗮 🛟 Matthews PaintManager 🖗	Color Software Beta App: 18200225	/ Data: 1.8.2003.16	Welcome,	Sys Admin Logout 🕜 👝 🛱	X
sparkle silver				Q	⊗
Paint Lines	Color Attribute ▼	s Color	System SORT Rele	vance 🔻 💾	≡
KOJIS SIGNS, INC R105522 SPARKLE SILVI SILVER	MATTHEWS PAINT 72806 SPARKLE SILVER METALLIC	MATTHEWS PAINT 75830 SPARKLE SILVER	AKZO 629 A-5 SPARKLE SILVER METALLIC	MATTHEWS PAINT MP86374 CPM 3296MA MET SPARKLE SILVER	
BRAND MP68956	BRAND MP72806	BRAND MP75830	BRAND MP72806	BRAND MP86374	
MATTHEWS PAINT 18074 SPARKLE SILVER MET.	MATTHEWS PAINT 21024 SPARKLE CHAMPAGNE SILVER	i MATTHEWS PAINT 21290 SPARKLE SILVER	i MATTHEWS PAINT 21291 SPARKLE SILVER	MATTHEWS PAINT 21437 LIGHT SPARKLE SILVER MET.	
BRAND MP18074	BRAND MP21024	BRAND MP21290	BRAND MP21291	BRAND MP21437	\sim

Revision Results:



Compare Formulas:

	Compare Selected 3 4 Clear selections				
Matthews PaintManager® Color Software Beta App: 18 FORCEFUL ORA	Welcome, Sys Admin Logout @ _				
MP NUMBER COLOR SYSTEM MP45454 MATTHEWS PAINT	Select the Tools Menu to				
All Paint Lines All Paint Finishes	tem				
WEBSITE (1) OTHER REVISIONS (1)					
1.0 1.1					
2 Compare Compare Select up to 4 formulas to compare.					

≡ ↔ Matthew 〈 Comp	rs PaintManager® Color Software Beta App: 182003.34 / Date: 1.8200 are Colors	Welcome, Sys Admin Logout Welcome, Sys Admin Logout
Col OEM Coo Color Nap		5 6
Color Syste Coo Descriptio	MATTHEWS PAINT te 1.0	MATTHEWS PAINT
Color Fam Match Da	ily Orange 6/23/2015	Orange 6/23/2015
Code Descriptio	n INCREMENTAL	INCREMENTAL
Toggle N9	42 662.6 g	662.6 g
View N20	2 252.8 g	252.8 g
N94	0 84.1 g	84.1 g
N93	0 22.0 g	22.0 g
	5. Change Volume	
	6. Change unit of measure	
		Remove from Comparison Proceed to Mixing
	Remove	Remove

Formula and Mixing:

	🚍 💠 Matthews PaintManager® Color Software Beta App: 18.2003.34 / Data: 18.2004.12 Welcome, Sys Admin Logout 🔞 👝 🛅 🗙						
	Formula & Mixing		For	mula Details	Mi	x Session	n 5454 ()
1	CLEAR Main Layer	CODE MP45454	PAINT	LINE PAINT FINISH	COMMENTS COMPUTER FORMULA NO/MIX		J4J4 V
	PRIMER	Baco			VOC S Cost	1 pt	nd v 💥 v
2	+Undercoat +Color +Clearcoat	ORDER 1 ×	CODE N942	DESCRIPTION GREEN YELLOW	9.01 Ibs/gai INCRE	MENTAL 331.3 g	CUMULATIVE 331.3 g
	3 Pour Target: Base Product	2 × 3 × 4 ×	N202 N940 N930	WHITE RED YELLOW LIGHT RED		126.4 g 42.0 g 11.0 g	457.7 g 499.7 g 510.7 g
4	- 1 + U.S. Pints 5 V	6					+ Reduction
7	Minimum						
	8 Mix Formula in: One Can						

- 1. Layers: The largest diamond is the selected layer
- 2. Add Layers: Access to layer Favorites, Master List, and new Color searches.
- 3. Pour Target: Mix quantity is calculated based on this selection.
 - Base Product: (For Color Only)
 - Includes toner only, no reduction components.
 - Used by Volume Estimator to calculate quantity per panel without reduction.

Total Product: Ready-For-Use quantity for Undercoats and Clearcoats.

- 4. Quantity: Select quantity for chosen Pour Target.
- 5. Unit of Measure: Change from fluid ounces to gallons, quarts, etc..
- 6. Volume / Gravimetric: Change from volume to weight for quantity selection.
- **7. Minimum:** Calculates the smallest formula that can be mixed based on components in the formula.
- 8. Mix Containers:

One Can: Base and Reduction components to be mixed in the same container in one step.
 Two Cans: Base product to be mixed in step one, reduction in a step two. This allows reduction components to be mixed in a separate can or to be added to the original can at a later time.

Formula Details:

■ ↔ Matthews PaintManager® Color Software Beta App: 182002.2		Welcome, Sys Admin Logout			
Formula & Mixing			Formula Details	Mix Session	
Main Layer	FOF CODE MP45454	PAINT	UL ORANGE : 454	54 14 15 LA NO/INI	16 17
+Undercoat +Color +Clearcoat				∮ VOC ∮ Cost 曲 S	iend 🔻 🗙 🔻
	Base			9.01 lbs/ga, 1 qt	1021.402 g
Pour Target: Race Product	ORDER	CODE	DESCRIPTION	INCREMENTA	CUMULATIVE
Four larget. Base Floduct	1 X	N942	GREEN YELLOW	662.6 g	g 662.6 g
	2 🗙	N202	WHITE	252.8 0	g 915.4 g
- + U.S. Quarts •	3 🗙	N940	RED YELLOW	84.1	9999.4 g
	4 ~	N930	LIGHT RED	22	1021.4 g
Minimum Mix Formula in: One Can	13				- Reduction
	Reduct	ion		7.49 lbs/ga 0.667 g	t 566.235 g
	ORDER	CODE	DESCRIPTION	INCREMENTA	CUMULATIVE
	5 ×	43270SP	UNIVERSAL CATALYST	297.1	1318.5 a
	6 ×	45280SP	WARM TEMPERATURE REDUCER	269.1	g 1587.6 g
	Total			8.40 lbs/ga 1.667	qt 1587.6 g

- 9. Reduction: Access to reduction Favorites and the Master List.
- **10. Base:** Calculated Base amount.
- **11. Reduction:** Calculated Reduction amount.
- **12. Total:** Calculated Total for Base plus Reduction amounts.
- **13. Product Indicators:**
 - "X" denotes there is not enough inventory to mix this product. (Only shows up if Inventory is selected in Settings.)
 - "L" denotes a limited use toner when present.
- **14. VOC:** VOC and HAPS information.
- **15.** Cost: Will display the cost and/or price depending on what is selected in Settings.
- **16. Send:** Print a formula label, formula paper printout, or send email formula.
- 17. Tools Menu:

Delete Layer: You can only delete the selected layer prior to mixing.

Save as a Custom Formula: Creates a Custom Formula from the selected layer.

Section 8: Mix Management

Mix Session:



Job Association:



Adding a Job:

🗮 💠 Matthews PaintManager® Color Soft	Ware Beta App: 1.8.2002.25 / Data: 1.8.2003.16		Welcome, Sys Admin Logout	•	_ 0	X
Job Association						
Please select or create a job to associate to the	Create Job		Add a Job	1	+ Jo	b
Filter Sign Order Filter 🔻	2 Enter Job	#	Due Date Ascending		•	≡
🚔 1234	SO Number (Required)					
	Due Date	Priority				
	Enter date (Optional)	ற Normal 🗸				
No mixes assigned	New Contact Existing Contact	Add a new or exi	sting			
	Contact Name	Customer. (Option	al)			
≞ 2	First Name	Last Name				
	Company					
	Company Name					
		4 Save Changes Cancel				
		-	-			
		Cancel				

Weigh on the Scale:

■ -{-> Matthews PaintManager® Color Software Beta App 1. 1 Place the can on the scale a	82002.25 / Data: 1.8.2003.16 Welcome, Sys nd press Continue	s Admin Logout 🔞 🔔 🗂 🗙
	FORCEFUL ORANGE : 45454 : MP4 CODE PAINT LINE PAINT FINISH COMMENTS MP45454 N N SATIN COMMUTER FORMULA NO/MIX MAIN LAYER	5454 🕡
	COLOR	1 qt
	REDUCTION	0.667 qt
	TOTAL	1.667 qt (Ready For Use)
	 Select continue when ready to weigh 	Shows the volumes for color, reducer (selected in mix session) and RFU
3 Virtual Scale Default Scale from Settings.	Continue	
Other scales can be selected		
if they are configured in Scale		
Settings.		

	⇔ _{Matthev} FOF	ws PaintManager®	® Color Sof	tware Beta App: 1.8.2002.	25/Data: 1.8.2003.16 : 45454	: MP454	welcon 154	ne, Sys Admin L	ogout 😮	
			co o	MPONENT 1 OF 6 N942 SREEN YELLOW	^{remaining} 20.7 g	poured 641.9 g	TOTAL 1.415 lbs / 3.5 lbs 0.659 qt / 1.667 qt			
		_		_			_			
						Magnifica	ation bubble			
						left to po	ur	20 [°]	ining 7 a	
Orde	r Code	Description					Target (Inc.)	Actual (Inc.)	Difference	Accuracy
1	N942	GREEN YELLOW	Product	being poure	d will be highlig	ghted	662.6 g	641.9 g	-20.7 g	96.9%
2	N202	WHITE					252.8 g	0.0 g	-252.8 g	0.0%
3	N940	RED YELLOW					84.1 g	0.0 g	-84.1 g	0.0%
4	N930	LIGHT RED					22.0 g	0.0 g	-22.0 g	0.0%
5	43270SP	UNIVERSAL CATALY	YST	Shows cataly	st added to mi	x	297.1 g	0.0 g	-297.1 g	0.0%
Wa	aste Mix	Pause Re	ebulk Formu	la			Skip	Previous	Next	Virtual Pour
	1	2	3				4	5	6	7

- **1. Waste:** Select to waste a mix. It this feature is configured to be enforced in Application Settings a waste reason will have to be selected. Otherwise it is optional.
- 2. Pause: The paused mix is added to the Mix Queue and flagged on the Job layer screen where the mix can be finished at a later time.
- **3. Rebulk Formula:** In the event of an over pour this option can be used to correct the formula. If selected the program will move back to the first component to correct components already poured.
- **4. Skip:** Allows the mixer to advance to the next component when it is not poured to minimum tolerance. This button is only available if "Under /Over Pour Formula" is selected in User Management.
- 5. Previous: User can select a previous component.
- 6. Next: Advance to the next component. When pouring the last component it changes to "Continue".
- **7.** Virtual Pour: This is a default scale that is used for demonstration purposes. It is configured in Scale Settings.

Note: Warning displayed if the paint can is removed from the scale before the mix is complete.



Mix Summary:

≡⇔	Matthew	s PaintManager® Color Software Beta App: 18.2002.25 / Data: 1.8.2003.16	Welcom	e, Sys Admin Log	gout 🕜 🗕	- 🗆 🗙
Ма	lix Su in Layer	Mmmary FORCEFUL ORANGE: 45454: MP45454 CODE PAINT LINE PAINT FINISH COMMENTS MP45454 N N SATIN COMPUTER FORMULA NO/MIX		1 Ø voc	2 ♦ Cost	3 A Send V
BASE		NTS Target: 1 qt Actual: 1 qt				
Order	Code	Description	Target (Inc.)	Actual (Inc.)	Difference	Accuracy
1	N942	GREEN YELLOW	662.6 g	662.7 g	0.1 g	100.0%
2	N202	WHITE	252.8 g	252.9 g	0.1 g	100.0%
3	N940	RED YELLOW	84.1 g	84.1 g	0.0 g	100.0%
4	N930	LIGHT RED	22.0 g	22.0 g	0.0 g	100.0%
REDUC	CTION CO	APONENTS Target: 0.667 qt Actual: 0.667 qt				
Order	Code	Description	Target (Inc.)	Actual (Inc.)	Difference	Accuracy
5	43270SP	UNIVERSAL CATALYST	297.1 g	297.1 g	0.0 g	100.0%
6	45280SP	WARM TEMPERATURE REDUCER	269.1 g	269.1 g	0.0 g	100.0%
TOTAL		Target: 1.667 qt Actual: 1.667 qt				
_	4		5	6		7
	Reweigh	Spl	it Mix	To Mix Session	Fir	nished

- 1. VOC: View VOC Information
- 2. Cost: View Cost and/or Price depending on selections in Settings.
- **3.** Send: Print Label via label or computer printer. Print or email the Mix Summary.
- 4. Reweigh: Return to the Weigh Screen.
- 5. Split Mix: Assign portions of mix to other Jobs. (See Job Management)
- 6. To Mix Session: Return to Mix Session.
- 7. Finished: Completes mix.

Split Mix:



Step	Step 1: Select jobs to be used for splitting the mix. Next Cancel							
	RO# CUSTOMER VEHICLE PRIORITY DUE DATE							
	1000	Normal						
	2000	Normal						
	2002 Select one of more jobs to split	Normal						
~	2003 the mix to	Normal						
	2004	Normal						
~	2005	Normal						

- 1. Select one or more Jobs.
- 2. Next: Hit Next to continue to Split Mix.



- 3. Enter amount to split.
- 4. Weigh: (optional) Weigh the product to split.
- 5. Remove: Delete Job from the Split.
- 6. Next: Hit Next when ready to apply Split.



- 7. Split Mix: Continue Split Mix to additional Jobs.
- 8. Add to Pre-Mixed Inventory: To use for future jobs not yet created.
- 9. Finish: Leaves the remaining amount on the original Job used to begin the Split.

Mix Queue Active Tab:

All mixes are captured in the Mix Queue. Mixes in process are captured in the Active tab and completed mixes are moved to the Mix History tab. Mixes that take place on Jobs can be viewed in the Mix Queue or in the individual Job screen. Mixes not recorded on a Job can be located here in the Mix Queue.



1. Filter by mix types:

All Mixes Paused Mixes Mixes not Started Unreduced Mixes

2. Filtered Search:

Description

Customer

- 3. Date filtered search
- 4. Sort Options
- 5. Tools Menu

Waste: Only available for mixes that are started
Reduce Now: Only available for mixes with base product already mixed
Remove: Available for mixes that not started (Nothing has been mixed yet)
Select: Proceed to the Formula and Mixing screen
View Job: Navigate to the job associated with the mix
Mix Summary: Proceed to the Mix Summary screen

6. Remove/Waste: Select multiple mixes to be removed or wasted. Mixes not started can be removed. Mixes started can be wasted.

Mix Queue Mix History Tab:

All mixes are captured in the Mix Queue. Mixes in process are captured in the Active tab and completed mixes are moved to the Mix History tab. Mixes that take place on Jobs can be viewed in the Mix Queue or in the individual Job screen. Mixes not recorded on a Job can be located here in the Mix Queue.

🗮 💠 Matthews PaintManager® Color Softw	are Beta App: 1.8.2008.38 / Data: 1.8.2009.14	Welcome, Sys Admin Logout	0 _ 🗆 X
Mix Queue		Remove/Waste	
Active		Mix History	
From 8/12/2020	D 10 9/11/2020 13	Search SORT Created	Date Descending 🔻
	No Mix History		
	NO MIX HIStory		

- 1. Customer search
- 2. Date range search
- 3. Sort options
- 4. Tools menu

Waste Mix: Available for mixes not already wasted. (Wasted mixes cannot be un-wasted.) Mix More: Not available for mixes that have been wasted.

Mix Summary: Navigate to the Mix Summary.

View Job: Navigate to the Job screen.

5. Remove/Waste: Select multiple mixes to be removed or wasted.

Mixes not started can be removed.

Mixes started can be wasted.

Pre-Mixed Inventory:

This inventory is a comprised of two kinds of mixes.

- **Internal Inventory:** Formulas mixed with product in the mixing room added by selecting the "Add to Pre-Mixed Inventory" option after selecting to Mix on the scale. These mixes deplete the mixing room inventory and will be noted on the Inventory and Pricing screen. They will then be depleted from Pre-Mixed Inventory in whole or in part at a later time and potentially directed to one or more Jobs.
- **External Inventory:** Example: Formulas mixed by Jobbers or a PPG blend center added here. This added product does not create an increase to the internal inventory seen on the Inventory & Pricing screen. These mixes are then depleted from Pre-Mixed Inventory in whole or part at a later time and potentially directed to one or more Jobs. These mixes are added from the Formula Details screen on the Tools menu or using the +Manual Mix on the Pre-Mixed Inventory screen.



Manual Mix added to Pre-Mixed Inventory:

- 1. + Manual Mix: Used to add a mix from external sources.
- 2. Tools Menu:

Waste: Waste the mix. (Once wasted it cannot be un-wasted.)
Mix Summary: Navigate to the Mix Summary screen.
Transfer Mix: Transfer the entire mix to a Job.
Split Mix: Transfer all or part of a mix to one or more Jobs.
Reduce All: Reduce the entire mix potentially adding it to a Job.
Reduce Partial: Reduce a partial amount potentially adding it to a Job.





Adding a Mix from the Pre-Mixed Inventory Screen:

🔳 💠 Ma	tthews PaintManager® Color Software Beta App 182012	6 / Data: 1.8 2012.27	Welcome, Sys Admin Lo	ogout 🕜 🗕	□ ×
< Ρ	re-Mixed Inventory		+ Manu	ual Mix	
Status	Description	Amount	Mixed Date	Mixed By	
\bigcirc	JOHN DEERE GREEN : 33317 : MP33317 (Main Layer)	0.7 gal	12/4/2020 12:01:36 PM	Painter 1	* •
\bigcirc	FLASH RED : MP12019 : MP12019 (Main Layer)	1 gal	1/5/2021 8:39:53 AM	Sys Admin	* •
\bigcirc	STEAMBOAT BLUE : MP25133 : MP25133 (Main Layer)	3 gal	1/5/2021 8:40:54 AM	Sys Admin	* •
Θ	RATTLEBOX YELLOW : MP05185 : MP5185 (Main Layer)	1 gal	1/5/2021 8:41:41 AM	Sys Admîn	* •
	206 C - C COLORS : 206 C - C COLORS : MP245 (Main Layer)	3 qt	1/5/2021 8:43:49 AM	Sys Admin	* •

Adding a Mix from the Formula Details Screen:

It is much simpler to add mixes to the Pre-Mixed Inventory from this screen. Look up the formula and select the "Add to Pre-Mixed Inventory" option on the Formula Details screen Tools menu.

$\equiv +^{\oplus}_{1^{2^{n}}}$ Matthews PaintManager ® Color Software Beta App 182012	6 / Data 1820	12.27		Welcome, Sys Admin Log	gout 🕜 🗕 🗇 🗙
Formula & Mixing Main Layer +Undercoat +Color +Clearcoat	206 CODE MP78318	C - PAINT N	Formula Details PLUS SERIES C : 206 LINE PAINT FINISH COMMENTS N SATIN R134121 AD DISPLAY SYSTI	Mix S C - PLUS S EM, RS TO PMS+, NS, KS, 2- VOC Ocst	ession SERIES C 1 18-14 A Send V XV
	Base			8.82 lbs/g	Delete Selected Layer
Pour Target: Base Product	ORDER 1 2 3 4	CODE N930 N947 N914 N202	DESCRIPTION LIGHT RED SCARLET DARK RED WHITE	1	Save as Custom Formula Add To Pre-Mixed Inventory + Reduction

Section 9: Job Management & Job Costing

Jobs Main Screen Tile View – Active or Open Jobs:



Job Main Screen – Job History or Closed Jobs:

The Job History screen comes up blank initially and a date range must be selected to populate the screen.



Add a New Job:

🗮 💠 Matthews PaintManager® Color Soft	Ware Beta App: 1.8.2002.25 / Data: 1.8.2003.16		Welcome, Sys Admin Logout 🕜 🗕 🛅 🗙
Sobs	Create Job		1 + Job
Active			History
From 2/11/2020 2	SO Number Enter Jo	b Number	Search Search
sign Order Filter	Due Date *Required	Priority	SORT Due Date Ascending
3	Enter date (Optional)	図 Normal (Optional)	4
	New Contact Existing Contact	t 5 (Optional) Enter a	a new or existing contact
	Contact Name		
	First Name	Last Name	
	Company		
	Company Name	6	
		Save Cancel	

Job Layer Tab:

ا 🔶 🔳	Matthews Pair	ntManager® Color Software Beta App: 1.8.2002.25 / Data: 1.8.2003.16		Welcome, Sj	vs Admin Logout 🕜 🗕 🗂 🗙
<=	1234	Customer	Du	e Date Priority Normal	Status Open 1
\$	←	Layers Tab		2	+ Clear/Undercoat + Color
1	Status	Description	Amount	Mixed Date	Міхед Ву
Q	3	123 C - C COLORS : 123 C - C COLORS : MP59554 (Main Layer) - Satin MAP	0.63 qt	3/4/2020 6:19:07 PM	Duane D 🗙 🔹
\$	-	CINNAGOLD DUST CUSTOM : R162871 CINNAGOLD DUST CUSTOM : MP91100 (Main Layer)	0.635 qt	3/9/2020 10:03:30 AM	PabloP 🗙 🔹
\odot		FORCEFUL ORANGE : 45454 : MP45454 (Main Layer) - Satin MAP	1.667 qt	3/12/2020 1:08:10 PM	Duane D
	4 🧧	Gray Epoxy Primer 2.1 VOC (PRIMER)	1 qt		* •
	0	MAP Gloss Clear (CLEAR) 1. Edit Job Information 2. Add additional layers 3. Layer marked as wasted 4. Layer marked as rework 5. Layer Tools menu options (See	1qt e next scre	en capture for d	5 X V

Job Layer Tools Menu Options:

(Layer Tool Option availability depends on status of layer)



Sundries Tab:

<	Customer Sundry Tab		Due Date Select + +Sundry I	Priority Normal Sundries or Kit to add to a	s (Dpen
	Kit	Product Code	Product Description	job Sku	+ Sun Qty	Added By
→ Q	Bumper Kit	SU4903 SU4903	ADVANCED PLASTIC BO	SU4903/04 SU4903/04	6.00 floz 4.00 floz	Sysadmin X V
t (6	Item added as Sundry Kit)	Item added as Sundries		Use drop Edit or	o down to Remove

Contact Tab:



Notes Tab:



Job (\$) Financial Tab:

≡ �	Matthe	ws Pair	ntManager@	Color Software Beta App: 1.8.2002.25 / Data: 1.8.2003.16		Welcome, Sys Adm	in Logout 🕜	_ [3 X
<	N 12	34	Customer		Due Date	Priority Normal	_{Status} Open	3	4
>	ST/	ATUS	DATE MIXED	PRODUCT DESCRIPTION		MIXED BY	AMOUNT APPLIED	соѕт	PRICE
	1	Spray	/able						
Q			3/4/2020	123 C - C COLORS : 123 C - C COLORS : MP59554 - Satin MAP		Duane D	0.63 qt		0.0
\$			3/9/2020	CINNAGOLD DUST CUSTOM : R162871 CINNAGOLD DUST CUSTOM : MP91	1100	PabloP	0.63 qt	\$35.05	0.0
€ (3/12/2020	FORCEFUL ORANGE : 45454 : MP45454 - Satin MAP		Duane D	1.67 qt		
Ð	(С		Gray Epoxy Primer 2.1 VOC			1.00 qt		
	(С		MAP Gloss Clear			1.00 qt		
							Sprayable Total	\$35.05	\$0.00
						Non-St	Sundries Total pravable Estimate	\$0.00 \$0.00	\$0.00 \$0.00
							Invoice Total	\$35.05	\$0.00
							Overall Margin		0.0%
							Update N	lissing P	rices

Sprayable: This section lists all materials mixed across the scale.

Sundries: If applicable, this section lists all sundries added from the Sundries tab.

Cost: Displays if selected in Settings-Application Settings-Pricing.

Initially populates with the cost in Inventory & Pricing at the time the mix was completed.

If discounts are applied to cost in Inventory & Pricing they will be reflected here.

Price: Displays if selected in Settings-Application Settings-Pricing.

Initially populates with the price in Inventory & Pricing at the time the mix was completed.

If margin percentages are applied to price in Inventory & Pricing they will be reflected here.

Total Sprayables: Total of the sprayable section.

Total Sundries: Total of the sundries section.

Non-Sprayable Estimate

This is calculated as a percent of the Job Total. This calculation will subtract the Sundry Total to ensure it does not exceed the non-sprayable percent of Job Total. Based on the value in the Settings-Application Settings/Jobs tab at the time the Job is created. If the Sundry Total exceeds this %, sundries are reported as actual and the Non-Sprayable Estimate will be zero. This can be adjusted on this screen using the edit button.

Job Total: Sprayable Total + Sundries Total + Non-Sprayable Estimate.

Overall Margin:

Calculated profit margin from the difference between price and cost on this screen. Wasted and rework layers have cost but no price which lowers the overall margin.

Run Invoice:

See Details in the next section.

Run Invoice Options:

•

- The Default Sign Order Invoice: Non-sprayables are included waste and rework are not.
 - Other templates created for the Sign Order Invoice in Reporting will be available here.
 - Example: Waste and rework included Non-sprayables not included

Note: If the non-sprayable percent is changed to zero the description and zero amount will not print on the invoice.

- Matthew	∕s PaintMa	nager® Colo	r Software Beta App	: 1.8.2008.38 / Data: 1.8.20	09.20		И	/elcome, Sys Admin Logout	0 _	. 🗂
<	>	1 / 1 G	९ ११७.	2%						
Sign O	rder In	voice			Customer: test job		PPG II	ndustries		
Tost Job							19699	Progress Drive		
Status Date Created			Date Closed				Strong	sville OH, 44149		
Open	9/11/2	020 4:23 PM	N/A							
Connected									_	
Sprayable	items									
Mix I	Date	Category	Description				Mixed By	Amount Applied	Price	
9/11/202	0 3:40 PM	Color	VERDEGRIS	13832 : MP13832			Sys Admin	1.00 qt	\$43.	77
9/11/202	0 3:40 PM	Primer	Gray Epoxy	Primer 2.1 VOC			Sys Admin	1.00 qt	\$55.	21
9/11/202	0 3:39 PM	Clear	MAP Gloss (lear			Sys Admin	1.00 qt	\$0.	00
							Sp	rayable Items Total	\$98.	98
Non-Spra	yable Ite	ms								
Date A	dded	Sundry Kit	OEM Code	Description		SKU	Added By	Quantity	Price	
9/11/202	0 3:29 PM		CAN/01	Paint Can, 1Gal	on	CAN/01	Sys Admin	1.00 ea	\$0.	.00
							Non-	Sprayables Subtotal	\$0	.00
								Invoice Total	\$98	.98

Sign Order Invoice:

		vve	come, Sys Admin Logout	0 -	
< > 1 /1 Q	२ 117.2% र 📅 🖸				
Sign Order Invoice	Customer: N/A	PPG In	dustries		
Scaler Test		19699 P	rogress Drive		
		Strongs			
Status Date Created Date	Closed				
Status Date Created Date Dpen 3/13/2020 2:44 PM N/A	Closed				
Status Date Created Date Open 3/13/2020 2:44 PM N/A Sprayable Items	Closed				
Status Date Created Date Open 3/13/2020 2:44 PM N/A Sprayable Items Mix Date Category D	Closed	Mixed By	Amount Applied	Price	
Date Created Date Open 3/13/2020 2:44 PM N/A Sprayable Items Mix Date Category D 3/13/2020 10:46 AM Color F	Closed Vescription ORCEFUL ORANGE : 45454 : MP45454	Mixed By Sys Admin	Amount Applied 1.01 qt	Price \$47.42	
Status Date Created Date Dpen 3/13/2020 2:44 PM N/A Sprayable Items Mix Date Category D 3/13/2020 10:46 AM Color F	Closed Pescription 'ORCEFUL ORANGE : 45454 : MP45454	Mixed By Sys Admin Spr a	Amount Applied 1.01 qt ayable Items Total	Price \$47.42 \$47.42	

Print

Sends the report to the report printer designated in Settings-Print Settings.

Navigation and Sizing Controls:

Job Information:

New: One line for each mix.

New: Time as well as date of mix.

New: Product category.

Customer Information

Shop Information

Sprayable Items

Sundry Items

Non-Sprayable Refinish Materials:

The description that shows up on the invoice comes from Settings/Application Settings/Jobs/Non-Sprayable Line Item Description field.

Is the Non-Sprayable % of Job Total minus any sundries.

Non-Sprayables Subtotal: Actual Sundries + the remaining Non-Sprayable Estimate from the Job Financial Screen.

Remember: If there are any sundries, they are subtracted from Non-Sprayable estimate.

Invoice Total: Total for all the price elements of Sprayables + Non-Sprayables(includes sundries), from the Job Financial(\$) screen.

Close: Return to the Job Financial(\$) screen.

Transaction History Tab:

The job transaction tab keeps a record of each change made to the job.

≡	Matthews PaintManage	er® Color Software Beta App: 1.8.2002.25 / Data: 1.8.2003.16		Welcome, Sys Admin	Logout ?	- 🗆 X
<=	1234 Customer		Due Date	Priority Normal	Status Open	ľ
\$	History					
1	DATE/TIME	ACTIVITY				USER
0	3/12/2020 1:08:10 PM	Mixed FORCEFUL ORANGE : 45454 : MP45454				Sys Admin
¢	3/12/2020 1:06:07 PM	MAP Gloss Clear has been added				Sys Admin
3	3/12/2020 1:06:07 PM	FORCEFUL ORANGE : 45454 : MP45454 has been added				Sys Admin
G	3/12/2020 1:06:07 PM	Satin MAP has been added				Sys Admin
	3/12/2020 1:06:07 PM	Gray Epoxy Primer 2.1 VOC has been added				Sys Admin
	3/9/2020 10:03:37 AM	I CINNAGOLD DUST CUSTOM : R162871 CINNAGOLD DUST CUST	OM : MP91100 layer wasted			Painter 1
	3/9/2020 10:02:45 AM	CINNAGOLD DUST CUSTOM : R162871 CINNAGOLD DUST CUST	OM : MP91100 has been added			Painter 1
	3/4/2020 6:19:14 PM	123 C - C COLORS : 123 C - C COLORS : MP59554 layer wasted				Sys Admin
	3/4/2020 6:15:26 PM	123 C - C COLORS : 123 C - C COLORS : MP59554 has been add	ed			Sys Admin
	3/4/2020 6:15:26 PM	Satin MAP has been added				Sys Admin
	3/4/2020 6:14:51 PM	Job Created				Sys Admin

Ready for Use Selections from the Dashboard or Main Menu:

When jobs are not used, if the user returns to the Dashboard after mixing, the ability to add layers from the Mix Session is lost. In this situation, or at any time, the user can access Ready for Use favorites from the Dashboard or Main Menu. **As a reminder:** Second layers for tri-coat formulas can be accessed from the Mix Queue in the event access to the Mix Session is lost when not using Jobs.





Selecting Undercoats and Clearcoats:

🗮 ⊹ Matthews PaintManager® Color Softw	CIFE Beta App: 1.8.2002.25 / Data: 1.8.2003.16	Welcome, Sys Admin Logout	? _ □	X
Keady For Use	Automatically defaults to the Favorites Tab			
1 Favorite:		Master List		
All Categories 🔻 All Paint Lines 🔻	All Yoduct code search		2	⊗
Filter product category		Select desired RFU		1
N SATIN 43270SP 45280SP 3 1 1	Satin M/	combination and	Select 🕨	
VOC Category:		proceed to mixing		1
42228SP 43270SP 6396SP 3 1 1	MAP Sa	tin Clear	Select	
VOC Category: Clear Coating				
42208SP 43270SP 45280SF 3 1 1	MAP Gl	oss Clear	Select	
VOC Category: Clear Coating				

Custom Formula Main Screen:



Creating a New Custom Formula:

From the Custom Formula screen select the +Formula button. You will then have to fill out all the required and optional formula information, add toners & quantities and save your formula.

- 1. Add New Custom Formula.
- 2. Search for a Custom Formula

Color code, color name, source.

Can combine multiple criteria with a space in between each one.

Follow search criteria order

- 3. Search or Clear Search
- 4. Filter Options

Paint Lines represented in all of the custom formulas.

Specific customer.

Formulas created in My Shop or Online formulas shared thru collaboration.

Formulas linked to original color or those not linked.

- 5. Sort Options
- 6. View Options: (Grid or List)
- 7. Compare

Select up to 4 custom formulas derived from the same paint line and paint code to compare.

- 8. Edit: (More on this later)
- 9. Select and Mix: Touch or click on the tile but not on the edit symbol.

Creating a Custom Formula From an Existing Formula:



Creating a Custom Formula From Scratch:

+ Formula

From the Custom Formula screen select the +Formula button. You will then have to fill out all the required and optional formula information, add toners & quantities and save your formula.



Custom Formula Edit — Components Tab:

\equiv \Leftrightarrow Matthews P	PaintManager® C	olor Software Beta	App: 1.8.2002.25 / Data:	1.8.2003.16	We	lcome, Sys Admin Lo	3 🤉 🗕	4 X
< Test 2:1	ēst2	st2					iave C	ancel
Color Description	Test 2		_	Color Code Test2		J VOC	Cost	× •
	Components			Details		Contac	ma	
PAINT LINE		AMOUNT		COMPONENT	%	GRAMS [INC.]	ORDER	DELETE
N		0.19 qt		N911 VIOLET	63.0	- 113.0 +		×
Filter Com 8	Select co	mponents t	o add 🛛 🕺	N931 TRANS RED	26.4	- 52.0 +		×
42208 GLOSS CLEAR	42228 SATIN CLEAR	287112 SUEDE ADDITIVE MEDIUM		N929 CARBON BLACK	7.2	- 13.0 +		×
287113 SUEDE ADDITIVE	287190 CRIMSON PEARL	287192 OPAL BLUE PEARL		N923 BLACK	3.3	- 6.0 +		×
287193 GOLD DUST PEARL	287195 FROST WHITE PEARL	287196 RUSSET PEARL				9	10	11
287197 COPPER PEARL	287750 EXEMPT FLATTENING	DX41 FLAMBOYANCE WHITE						
FACTORY PACK	N202 WHITE	N911 VIOLET	\sim	12	To Formula and N	lixing		

- 1. Color Description: Required
- 2. Color Code: Required
- 3. Save
- 4. Cancel
- 5. VOC
- 6. Cost

Price Code

Cost

Price

- 7. Tools Menu: Delete custom formula
- 8. Filtered Search
- 9. Change Toner Amount
- 10. Order: Move Toner in List
- 11. Delete Toner
- **12. To Formula and Mixing:** To mix the formula on the scale.

Details Tab:

In the event a custom formula was entered from scratch, you can make entries here as needed to help with future searches, pricing, and reference information.

Custom formulas created from an existing code will automatically populate these entries.

Section 11: Sundries and Sundry Kits



Enable a Matthews Product for Sundry Use:

To be able to add a product as a sundry, you must enable it.

🔳 💠 Matthew	/s PaintMana	ger® Color Software n			Welco	ome, Sys Adm	in Logou	t 🕜 .	– 🗆 X
< Inve	ntory a	& Pricing Select the	Liquid Inventory Tab		5	Search	for	produ	rders
	Liquid Inv	ventory 1	Sundries			SL	inaries r		
III Levels	🗸 Cost	All Paint Lines All Categories 	▼ All Pricing ▼ All Inventory		2		-		?) 🗙 ▾
PAINT LINE	CODE	DESCRIPTION		SIZE	PRICE LIST	DISCOUNT	COST	MARKUP	PRICE
 Additive 									
5 Paint Lines •••	287112	SUEDE ADDITIVE MEDIUM		1 qt	\$78.24	0 %	\$78.24	0 %	\$78.24
5 Paint Lines •••	287113	SUEDE ADDITIVE		1 qt	\$78.24	0 %	\$78.24	0 %	\$78.24
4 Paint Lines •••	287750	EXEMPT FLATTENING PASTE	Select the product vo	u	\$231.25	0 %	\$231.25	0 %	\$231.25
2 Paint Lines •••	47888	FLATTENING PASTE	wich to onable		\$97.79	0 %	\$97.79	0 %	\$97.79
▼ Clear									
2 Paint Lines •••	42208	GLOSS CLEAR		1 gal	\$176.03	0 %	\$176.03	0 %	\$176.03
2 Paint Lines •••	42228	SATIN CLEAR		1 gal	\$180.63	0 %	\$180.63	0 %	\$180.63
2 Paint Lines •••	42260	BRACO CLEAR		1 gal	\$203.64	0 %	\$203.64	0 %	\$203.64
2 Paint Lines •••	42900	MATTE CLEAR		1 gal	\$179.48	0 %	\$179.48	0 %	\$179.48
									\sim

Continued on next page.

🔲 💠 Matthews Pain	tManager® Color Softw	are Beta App: 1.8.2002.25 / Da	ta: 1.8.2003.16		Welcome, Sys Admin Logout 🕐	_ 🗆 X
< Invento	ory & Pricing		5	Save Chang	ges	
287112 : SU	EDE ADDITI\	/e medium			Save and Close	Save Cancel
PAINT LINES						
5 Paint Lines 🕡	28	37112 : SUEDE ADDI [*] 0 0 Quarts	TIVE MEDIUM			
CATEGORY Liquid	SUBCATEGORY Additive		UNITS PER CARTON 6 x 1.00 qt	REORDER		
PRICE LIST \$78.24	DISCOUNT 0 % MARKUP 0 %	COST \$78.24 PRICE \$78.24	UNIT COST \$78.24/qt UNIT PRICE \$78.24/qt	0.00		
sku 287112SP/04					Amount on Hand	
On Order	PRODUCT IN USE	PRICING CALCULA	TION		0.00	
0.00	CAN ADD TO SUNDRY	Default KIT		MINIMUM AMOUNT 0.00		
	4 Check	o enable			AMOUNT ON HAND	

Create a non-Matthews Sundry:

≡ 💠 Matthews Pair	ntManager® Color Software P	1op:18.2003.25 (D. H. 10.2003.65	Welcome, Sys Admin Logout 🔞 🔔 🗂 🗙
< Invento	ory & Pricing	1 Select Sundries Tab	Prders
Liq	uid Inventory	Sundries	2 Select Tools Werld
III Levels 🛷 🐼	Cost All Manufacturers	All Categories All Pricing	Product code search
COLOR SYSTEM	CODE	DESCRIPTION	SIZE PRICE LIST DISCOUNT COST MA Manage Pricing
 Additive 			Manage Levels
T Daint Can	287112	SUEDE ADDITIVE MEDIUM	1 qt \$78.24 0 % \$78.24 + Sundry
• Paint Can	CAN/01	Paint Can. 1 Gallon	1 ea \$0.00 0 % \$0.00 0



- 1. Sundries Tab
- 2. Tools Menu: Select +Sundry
- 3. Product Information
- 4. Manufacturer: Used for filtering on the Sundries tab.
- 5. Subcategory: If you are adding a container you want to be used with the Can Management function you must select "Paint Can" and item 11 will automatically be selected. Can Management provides suggested container size for mixing and adds cost to Jobs.

6. Price List: This is the cost the customer pays for the item.

- 7. SKU: Used for ordering.
- 8. UOM: Select option to match container size.
- 9. Pack Size: Quantity for selected UOM. Example: UOM is each, pack size might be 25. (25 scuff pads in a box/pack)
- **10. Units Per Carton:** How many units in a carton/ case, used for inventory ordering.
- **11. Container:** Is automatically checked if you select the subcategory Paint Can.
- **12. Pricing Calculation:** Default pricing for all Sundries or designate a custom price or percent.
- 13. Save and Close

Create a Sundry Kit:

➡ ↔ Matthews PaintManager® Color Software Beta App Matthews PaintManager® Color Software Beta App Inventory & Pricing	p ^c 18200225/7 1 Select Sundries Kits	Tab Physical Inventory Orders
Liquid Inventory	Sundries	Sundries Kits
		SORT Name, A - Z 💌 🔀 💌
	1	2 + Sundry Kit Add Sundries from Import
	1	the Tools Menu

➡ 🕂 Matthews PaintManager® Color Softwar	'e Beta App: 1.8.2002.25 / Data: 1.8.2003.16	Welcome,	; Sys Admin Logout 【) _		X
Inventory & Pricing			Physical Invento	хy		
New Sundry Kit	Add Kit name and code	4	Add sundrie	s	Cance	2I
SUNDRY KIT NAME	SUNDRY KIT CODE			1		
				•	Sundrie	s
PRequired CODE DESCRIPTION Required		ON-HAND QTY UOM	F	EFINISH	PRICE	

Se	elect	sundries t	o add	_		-		
	Filter			6		7		
	5 Pa	aint Can	Select Products to add to Kit	Select Qua	intity	Select Unit Measure	: of	
	~	CAN/01 can/01	Paint Can, 1 Gallon	- 1	+	Each	•	
	~	CAN/04 can/04	Paint Can, 1 Quart	- 4	+	Each	·	
		CAN/05 can/05	Paint Can, 5 Gallons					
		CAN/08 can/08	Paint Can, 1 Pint					
		CAN/1L can/1l	Paint Can, 1 Liters					_
	_	CAN/2 5	I Paint Can 25 liters					\sim
					8	Save		Cancel

🔳 💠 Matth	ews PaintManager® Colo	Welcome	r, Sys Admin Loqout 🕜 🗕 🗐 🗙		
< Inv	entory & Prid	cing		Sav	e changes
New St	undry Kit				Save Cancel
SUN	IDRY KIT NAME	SUNDRY KIT CODE	_	Add more prod	lucts
Misc		Materials			+ Sundries
PRODUCT CODE	DESCRIPTION		ON-HAND	QTY UOM	REFINISH PRICE
287112	SUEDE ADDITIVE MEDIUM		0.00 qt	1.00 qt 🔻	\$78.24
CAN/01	Paint Can, 1 Gallon			1.00 ea 🔻	\$0.00
		Make as	liustmonts		
		IVIARE at	ijustments		Remove products

Matthews PaintManager Matthews Paint Matthews	® Color Software Beta App: 1.8. Pricing	Welcome, Sys Admin Logout 🕜 👝 🖻 🗙 Physical Inventory Orders	
Liquid Invent	ory	Sundries Kits	
			SORT Name, A - Z 💌 🗙 💌
Materials : Misc SUEDE ADDITIVE MEDI 1.00 qt Paint Can, 1 Gallon 1.00 ea Cost: \$78.24 Price: \$78.24	Kit is now rea to a Job	dy to add	

Cloning a Kit:

Cloning a kit is a fast way to create a new kit by duplicating an existing kit, make adjustments and save as a new kit. This is ideal when you want to create kits with similar components and with different quantities.

Example: You want to make two kits that all contain the same but at different amounts. You can create a small and large kit quickly using cloning.

≡ ↔ Matthews PaintManager® Color Software Beta App	4 [™] → Matthews PaintManager® Color Software Beta App: 18.2002.25 / Data: 18.2003.16			
Inventory & Pricing	Physical Inventory Orders			
Liquid Inventory	Sundries Kits			
		SORT Name, A - Z 💌 🔀 💌		
Materials : Misc SUEDE ADDITIVE MEDI 1.00 qt Paint Can, 1 Gallon 1.00 ea	kit you wish			
Cost: \$78.24 Price: \$78.24				



	ews PaintManager⊄	B Color Software Bet	ta App: 1.8.2003.	34 / Data: 1.8.20	004.28	Welcome, Sys Admin Logout	2 _	
Clone	Enter new ki name and co	it IG de PCQT ²	1		5	Save Changes		Orders
SUNDRY	KIT NAME	SUNDRY KIT CODE	Ē				÷	Sundries
P Required CODE	DESCRIPTION Re	quired	ON-HAND	QTY	иом			CE
CAN/01	Paint Can, 1 Gallon		2.00 ea	1.00	ea 🔻	Adjust QTY and	\$0.0	• 🗙
CAN/04	Paint Can, 1 Quart		2.00 ea	4.00	ea 🔻		\$0.0	• 🗙

Adding Sundries to a Job:

From the Job Sundry tab you can choose to add an individual sundry or a sundry kit.

ger® Color Software Beta Ap	p: 1.8.2008.38 / Data: 1.8.2009.20		Welcome, Sys Adn	nin Logout 🕜 🔔 🗂 🗙
^{Customer} Testing-test job		Due Date	Priority Normal	Status Open
Product Code CAN/01	Product Description Paint Can, 1 Gallon	Sku CAN/01	Qty 1.00 ea	+ Sundries + Sundry Kit Added By Duane Do
undry: ch and filter for ct individual sur ose quantity. ct unit of measu Changes.	sundry items. ndries. ıre.	Adding a Sur Search ar Select ind Choose c Save Cha	ndry Kit: nd filter for dividual kits Juantity. nges.	a sundry kit.
	ger® Color Software Beta Ag Customer Testing-test job Product Code CAN/01 Andry: ch and filter for ct individual sur ose quantity. ct unit of measu Changes.	ger @ Color Software Beta App: 18.2008.38 / Data: 18.2009.20 Customer Testing-test job Product Code Product Description CAN/01 Paint Can, 1 Gallon undry: Product for sundry items. ct individual sundries. Desce quantity. ct unit of measure. Changes.	ger & Color Software Beta App: 18 2008 38 / Date 18 2009 20 Customer Due Date Product Code Product Description Sku CAN/01 Paint Can, 1 Gallon CAN/01 Andding a Sur CAN/01 Search are ch and filter for sundry items. Search are ct individual sundries. Select individual sundries. ose quantity. Choose quantity. ct unit of measure. Save Char Changes. Save Char	ger @ Color Software Beta Age: 18.2008.38 / Date: 18.2009.20 Welcome: Sys Adm Customer Due Date Priority Normal Product Code Product Description Sku Qty CAN/01 Paint Can, 1 Gallon CAN/01 1.00 ea Andry: Adding a Sundry Kit: Search and filter for ch and filter for sundry items. Select individual kits ct individual sundries. Select individual kits ose quantity. Choose quantity. ct unit of measure. Save Changes.

Section 12: Pricing and Pack Size for Job Costing

The purpose of this section is to show you how to setup pricing for costing. Inventory will only be covered for pack size because the size of container selected can have an impact on cost.

Sundries and Sundries Kits will be discussed in Section 12

Inventory and Pricing Main Screen:

≡ 💠 Matthew	vs PaintMana	iger® Color Software Beta App. 18.2002.25 / Data. 18.2003.16	Welcome, Sys A	dmin Logou	0.	_ 🗇	×
< Inve	entory	& Pricing				Ord	lers
	Liquid In	ventory 1 Sundries		Sundries K	iits		
<u>d</u> 2	🖉 Cost	All Paint Lines 🔻 All Categories 🔻 All Pricing 💌 All Inventory. 💌	Product code s	earch		7 3	< •
PAINT LINE	CODE	DESCRIPTION	SIZE	PRICE LIST	MARGIN	PRICE	
 Additive 							
5 Paint Lines •••	287112	SUEDE ADDITIVE MEDIUM	1 qt	\$78.24	0 %	\$78.24	_
5 Paint Lines •••	287113	SUEDE ADDITIVE	1 qt	\$78.24	0 %	\$78.24	
4 Paint Lines •••	287750	EXEMPT FLATTENING PASTE	1 ga	\$231.25	0 %	\$231.25	
2 Paint Lines •••	47888	FLATTENING PASTE	1 ga	\$97.79		\$97.79	
▼ Clear					3		
2 Paint Lines •••	42208	GLOSS CLEAR	1 ga	\$176.03		\$176.03	
2 Paint Lines •••	42228	SATIN CLEAR	1 ga	\$180.63	0 %	\$180.63	
2 Paint Lines •••	42260	BRACO CLEAR	1 ga	\$203.64	0 %	\$203.64	
2 Paint Lines •••	42900	MATTE CLEAR	1 ga	\$179.48	0 %	\$179.48	
							\sim

Liquid Inventory Tab

- 1. Cost View selection
- 2. Current Price and Pack size settings

Manage Pricing:

🚍 💠 Matthews PaintManager® Color Software Beta App 18200225/Data 182003.16 🦉 💶 🗇 🗙									×		
< Inve	entory	& Pricing								Orders	
	Liquid Inventory		Sundries				Sundries Kits				
III Levels	🗸 Cost	All Paint Lines All C 	ategories	 All Pricing 	 All Inventory 	•	Product code se	arch			
PAINT LINE	CODE	DESCRIPTION					SIZE	PRIC	5	Manage Pricing	,
 Additive 										Manage Levels	
5 Paint Lines •••	287112	SUEDE ADDITIVE MEDIUM					1 qt	\$78.24	0 %	Export	
5 Paint Lines •••	287113	SUEDE ADDITIVE					1 qt	\$78.24	0 %	Export	-
4 Paint Lines •••	287750	EXEMPT FLATTENING PASTE					1 gal	\$231.25	0 %	Import	_
2 Paint Lines •••	47888	FLATTENING PASTE					1 gal	\$97.79	0 %	\$97.79	
▼ Clear											
2 Paint Lines •••	42208	GLOSS CLEAR					1 gal	\$176.03	0 %	\$176.03	
2 Paint Lines •••	42228	SATIN CLEAR					1 gal	\$180.63	0 %	\$180.63	
2 Paint Lines •••	42260	BRACO CLEAR					1 gal	\$203.64	0 %	\$203.64	
2 Paint Lines •••	42900	MATTE CLEAR					1 gal	\$179.48	0 %	\$179.48	
											/

4. Tools Menu

5. Manage Pricing Option

Pricing Screen:

<u>Important</u>: Price is calculated from Cost on the Inventory & Pricing screen instead of Price List. If you enter a discount the price will be calculated from the discounted cost. This is a major departure from Legacy.

Price, cost, discount percent, and margin percent have different priorities on this screen.

- Custom product pricing and percentages cannot be overwritten by category or Liquid Default settings.
- Hatthews PaintManager® Color Software Beta App: 1.8.2003.34 / Data: 1.8.2004.4 Welcome, Sys Admin Logout 0 •••• MANAGE PRICING All Categories 🔻 All Pricing 🔻 oduct code search All Paint Lines 🔍 All Inventor Bulk Update 5 Select All 6 Clear Selection 7 Reset Percent 8 Reset Price Cancel LIQUIDS DEFAULTS PRICE LIST DISCOUNT 0.00 % MARGIN 30.00 % PAINT LINE DESCRIPTION CODE PACK SIZE PRICE LIST DISCOUNT COST MARGIN PRICE 13 PRICE LIST DISCOUNT 14 COST MARGIN HAS DEFAULT ~ ADDITIVE 10.00 % 0.00 % \$78.24 5 Paint Lines ••• 287112 SUEDE ADDITIVE MEDIUM 1 Quarts 10.00 % 70.42 0.00 % 70.42 SUEDE ADDITIVE Custom Cost/Price 1 Ouarts 5 Paint Lines ••• 287113 \$78.24 74.42 74.42 4 Paint Lines ••• EXEMPT FLATTENING PASCustom Percent Gallons 17 20.00 % 185.00 30.00 % 264.29 2 Paint Lines ••• 47888 FLATTENING PASTE 1 Gallons \$97.79 10.00 % 88.01 0.00 % 88.01

• Category percentages are not overwritten by Liquid Default settings.

1. Filtering Options

Filter by Paint Line, Product Category, Pricing, and Inventory

2. Search Bar

Use the Search bar to filter products.

3. Clear

Resets filtering options to default settings and clears the search field.

4. Bulk Update

Option to apply custom discounts and margins to multiple products. Additional option to override custom costs and prices.

Highlights the product line blue to signify custom discount and margin.

5. Select All

This option will select all the inventory items to perform actions on all products.

Example: Reset all custom costs and prices back to default.

Example: Reset all custom discounts and margins back to those set for Liquid Defaults.

6. Clear Selection

This will deselect any products you may have selected including all.

7. Reset Percent

Resets custom discounts and margins for selected products back to those set for Liquid Defaults.


8. Reset Price

Resets custom costs and prices for selected products back to Price List with any applied discounts or margins from Liquid Defaults.

9. Save or Cancel

Save and exit, or Cancel and exit.

10. Liquid Default Price List Discount

This entry will calculate a discounted cost from Price List to be applied to all products on the list except product categories and individual products with individual settings.

11. Margin

This entry will apply a margin calculated from cost, which may be discounted, and apply it to all products on the list except product categories and individual products with individual settings.

- **12. Product Categories:** Categories can be collapsed & expanded and a category filter can be applied.
- **13. Product Category Price List Discount:** This will apply a discount calculated from Price List specific to this product category and are not over written by the Liquid Default settings.
- **14. Product Category Cost Margin:** This will apply a margin calculated from the category cost which may be discounted with a category Price List Discount.
- **15. Has Default:** This must be selected to add category discounts and margins.
- 16. Product Custom Cost and/or Price: (Highlights product line yellow)

Custom costs and prices are not overwritten with category or Liquid Default settings.

Custom costs and prices are not affected by software updates and must be managed manually.

Custom entries can be reset back to Category or Liquid Default by selecting them and choosing the **Reset Price** button. (Filter by Custom Price, select items, then Reset Price.) or (Choose the Select All button then Reset Price.)

Use custom price and cost with caution as manually managing products is time consuming. Look at the next option and manage with a custom percent if possible.

17. Product Custom Percent: (Highlights product line blue)

Custom percentages are not overwritten with category or Liquid Default settings.

Custom percentages are not affected by software updates and must be managed manually.

Custom percentages can be reset back to Category or Liquid Default by selecting them and choosing the **Reset Percent** button. (To reset all custom percentages, choose Select All then Reset Percent button.)

Modify Pack Size for Accurate Pricing:

Selecting the pack size to match what is in the customer's inventory is important for job cost environments. Smaller containers of product cost more per ounce and may overstate cost measurements and prices for billing if the shop is using a larger container. Correct pack size ensures accurate numbers.

< Inve	ntory	& Pricing										Or	ders
L	iquid Invent	tory			Sundries					Sundri	es Kits		
II Levels	Cost	All Paint Li 🔻	All Catego	•	All Pricing	•	All Inven	to 🔻	Product co	de search	1		× •
PAINT LINE	CODE	DESCRIPTION					SIZE	PRICE LIST	DISCOUNT	COST	MARGIN	PRICE	Manage Pricing
 Additive 											2		Manage Levels
5 Paint Lines •••	287112	SUEDE ADDITIVE ME	DIUM				1 qt	\$78.24	10 %	\$70.42	0 %	.10.4z	Export
5 Paint Lines •••	287113	SUEDE ADDITIVE					1 qt	\$78.24	0 %	\$78.24	0 %	\$78.24	Export
4 Paint Lines •••	287750	EXEMPT FLATTENING	G PASTE				1 gal	\$231.25	10 %	\$208.13	0 %	\$208.1	Import
2 Paint Lines •••	47888	FLATTENING PASTE					1 gal	\$97.79	10 %	\$88.01	0 %	\$88.01	
 Clear 													
2 Paint Lines •••	42208	GLOSS CLEAR					1 gal	\$176.03	0 %	\$176.03	30 %	\$251.47	
2 Paint Lines •••	42228	SATIN CLEAR					1 gal	\$180.63	0 %	\$180.63	30 %	\$258.04	

Manage Levels Screen:

≡ 💠 Matthew	🚍 💠 Matthews PaintManager ® Color Software Beta App: 18.2003.34 / Data: 18.2004.4 🛛 🛛 Welcome, Sys Admin Logout 👔 💶 🗙								
MANAGE LEVE	LS All Paint Line	s 🔻 🖡	All Categories 🔻 🛛 All M	linimums 🔻 All	Inventory 🔻	287	3		
			Select All	Clear Selection	Not Used	Used	Save	Cancel	
USED CODE	DESCRIPTION		SKU	▼ PACK SIZE	QTY N	/IN	REORDER	ADD TO CART	
 Additive 				5					
✔ 287112	SUEDE ADDITIVE MEDIUM		287112SP/04	1 Quarts	0.00	0.00	0.00		
✔ 287113	SUEDE ADDITIVE	4	287113SP/04	1 Quarts	0.00	0.00	0.00		
✔ 287750	EXEMPT FLATTENING PASTE		287750SP/01	1 Gallons	0.00	0.00	0.00		
1. Select th	ne Tools Menu								
2. Select ma	anage Levels								
3. Enter filt	3. Enter filtered Search criteria in the Search bar.								
4. Products with dropdown lists offer multiple pack sizes for selection.									
5. The curre	ent selected Pack Size for	r this _l	product.						

Select Container (Pack) Size:

	🔶 Matthews	PaintManager® Color So	ftware Beta App: 1.8.2	2008.38 / Data: 1.8.	2009.14	Welcome,	Sys Admin	Logout 🕐	_		Х
MAI	NAGE LEVEL	.S All Paint Lines	All Categories	▼ All Mini	mums 🔻	All Invento	ory 🔻	Product cod	e search		
			2	Select All				Used	Save	Can	cel
USED	CODE	DESCRIPTION	SKU	PACK	SIZE	QTY	MIN	REORDER	ADD TO	CART	へ
•	Binder										
~	283320SP	SATIN VOC CATALYST	283320SP/04	▼ 1 Qua	arts	0.00	0.00	0.00			
~	283800SP	VOC MAP CATALYST	283800SP/04	▼ 1Qua	arts	0.00	0.00	0.00			
~	43270SP	UNIVERSAL CATALYST	43270SP/04	▼ 1Qua	arts	0.00	0.00	0.00			
~	43621SP	BRUSHING CATALYST	43270SP/04	1 Qua	arts	0.00	0.00	0.00			
~	43999SP	SLOW CATALYST	43270SP/01	1 Qua	arts	0.00	0.00	0.00			
~	6278SP	HIGH PERFORMANCE CATAL	6278SP/01	1 Gal	ons	0.00	0.00	0.00			
~	74735SP	ACTIVATOR	74735SP/01	1 Gall	ons	0.00	0.00	0.00			
~	74766SP	PT ACTIVATOR	74766SP/01	1 Gall	ons	0.00	0.00	0.00			
~	74781SP	HBEF ACTIVATOR	74781SP/01	1 Gall	ons	0.00	0.00	0.00			
~	MAP-LVX101	EPOXY HARDENER	MAP-LVX101/04	1 Qua	arts	0.00	0.00	0.00			
~	MAP-LVX270	MAP-LV CATALYST	MAP-LVX270/04	▼ 1 Qua	arts	0.00	0.00	0.00			
•	Cleaner										
											\sim

- 6. Select the product dropdown menu.
- 7. Choose the desired pack size.
- 8. Save when you are finished making your selections.

Section 13: Basic Inventory for Ordering and Receiving

Introduction

• This Section covers basic inventory which is recommended to manage liquid inventory with limited use of sundry items. Managing large number of sundries requires extensive manual entry and ongoing manual price management.

Benefits

- Using the Ordering and Receiving function requires maintaining an accurate inventory count which in turn will provide an accurate inventory valuation. This valuation would be available for facilities that require it.
- As product is poured on the scale it is deducted from inventory and reordering is triggered automatically.

Challenges

- All product must be weighed on the scale to ensure accurate use for reordering. If product is not mixed on the scale, reordering will not be triggered accurately and you may run out of product before it is reordered.
- Orders must be generated and must also be received accurately to maintain integrity with the process.
- Inventory counts will be needed periodically to ensure the actual inventory amounts agree with those in the software.

Inventory & Pricing Main Screen

🔲 💠 Matthe	Atthews PaintManager® Color Software Beta App: 18.2002.25 / Data: 18.2003.16						ys Adm	in Log	out ?		
< Inve	Inventory & Pricing							Physica	al Invento	ory Orders	
	Liquid Inv	ventory		Sundries			Sundries Kits				
III Levels	Cost	All Paint Lines 🔹 A	Il Categories	▼ All Minimums	▼ All Inventory ▼	Product cod	de sear	ch		🖉 🗙	
PAINT LINE	CODE	DESCRIPTION				SIZE	QTY	MIN	REORD	Manage Pricing	
 Additive 										Manage Levels	
5 Paint Lines •••	287112	SUEDE ADDITIVE MEDIUM				1 qt	0.00	0.00	0.00	Export	
5 Paint Lines •••	287113	SUEDE ADDITIVE				1 qt	0.00	0.00	0.00		
4 Paint Lines •••	287750	EXEMPT FLATTENING PASTE				1 gal	0.00	0.00	0.00	Import	
2 Paint Lines •••	47888	FLATTENING PASTE				1 gal	0.00	0.00	0.00	0.00	
▼ Clear											
2 Paint Lines •••	42208	GLOSS CLEAR				1 gal	0.00	0.00	0.00	0.00	
2 Paint Lines •••	42228	SATIN CLEAR				1 gal	0.00	0.00	0.00	0.00	
2 Paint Lines •••	42260	BRACO CLEAR				1 gal	0.00	0.00	0.00	0.00	
2 Paint Lines •••	42900	MATTE CLEAR				1 gal	0.00	0.00	0.00	0.00	

1. Liquid Inventory Tab

2. Levels View

Current view used to display inventory levels and ordering information.

3. Cost View

4. Filters for Product

Paint Line and Product Category filters.

5. Filter for Minimums

Filter list for all products with minimum quantity entries.

Filter list for products where minimums are at or below minimum.

6. Filter for Used/Not Used Inventory:

Selecting only the inventory items used in the facility helps to manage a much shorter list.

7. Search & Filter

As you type a product number the list will begin to filter.

- 8. Cancel all Filters & Searches
- 9. Collapsed Product Category
- **10. Expanded Product Category**
- 11. Tools Menu Manage Pricing
- 12. Tools Menu Manage Levels

Used to establish inventory ordering parameters.

13. Tools Menu Export/Import

Ability to export Inventory and Pricing setting for editing and importing into another install.

Managing Product Levels

Filters: Reviewed on previous section.

	🕂 Matthews	PaintManager® Color S	Software Beta App	o: 1.8.2003.34	4 / Data: 1.8.2004.30	Welcom	ne, Sys Admin L	ogout 🕜		X
MA	NAGE LEVEI	S 1 All Paint Lines	All Categories	▼ All	Minimums 🔻	All Inver	ntory 🔻 P	Product code	search 2	
			3	Select All	4 Clear Sele	ection 5	Not Usec 6	Used	Save Cance	el
USED	CODE	DESCRIPTION	SKU		PACK SIZE	QTY	MIN	REORDER	ADD TO CART	へ
▼	Additive									
~	287112	SUEDE ADDITIVE MEDIUM	287112SP/04		1 Quarts	0.0	0.00	0.00	9	1
~	287113 Mar	rked as Used	287113SP/04		1 Quarts	0.0	0.00	0.00		
~	267750	EXEMPT FLATTENING PASTE	287750SP/01		1 Gallons	0.0	0.00	0.00		
~	47888	FLATTENING PASTE	47888SP/01		1 Gallons	0.0	0.00	0.00		
~	491	CLEAR MATTE	491/01		1 Gallons	0.0	0.00	0.00		
•	Clear									
~	42208	GLOSS CLEAR	42208SP/01	8	1 Gallons	-0.0	0.00	0.00		
~	42228	SATIN CLEAR	42228SP/01		1 Gallons	0.0	0.00	0.00		
×	42260	BRACO CLEAR	42260SP/01		1 Gallons	0.0	0.00	0.00		
×	42900	Marked as Unused	2900SP/01		1 Gallons	0.0	0.00	0.00		
						10	11	12		

1. Filtered Search

2. Select All

This will select all products on the inventory list.

Effective tool when used with the "Not Used" and "Used" button explained above.

3. Clear Selection

Select an individual product once and it becomes selected, twice it becomes unselected. Multiple items can be selected individually or with the Select All button.

This button can be used to clear the selection of multiple items.

4. Not Used Button

5. Used Button

6. Used Designation

Items with a green check mark are selected and those with a red **X** are not.

7. Pack Size Selection

Pack size options are available only if there is a dropdown list present.

Pack size is important for pricing as larger pack sizes cost less per amount used.

Pack size for inventory is important to calculate usage and reordering correctly.

8. Add To Cart

Items can be selected here to be added to an order.

9. Quantity on Hand

This represents the amount of product currently in stock.

As product is weighed on the scale the amount poured is deducted from this amount.

This can be roughly calculated by picking up each can and entering an approximate volume.

The "Inventory Current Status" report can be used to document this process.

10. Minimum Quantity

Once the quantity on hand is diminished to this quantity, the program will trigger an order for this product.

11. Reorder Quantity

The program recommends ordering this amount when the quantity on hand reaches the minimum quantity.

Tips for Limiting the Inventory List to Products Used in a Facility

When you are managing inventory for ordering and receiving, it is a good practice to be able to show only the products being used in the facility on this screen. This is done by marking items as either "Used" or "Not Used", then filtering the screen for the "Used" items.

Here is a procedure to follow to make this easier:

- •Choose the "Select All" button.
- •Select the "Not Used" button to mark all products with a red X in the "Used" column.
- •Filter the list by product category and begin selecting the products used in the facility in each category.
- •As you select each product make sure to choose the correct pack size.
- •When you are finished you can use the filter to view "Used Inventory".
- •Now you are ready to establish quantity on hand, minimum reorder point, and reorder quantity for each item.

Managing Orders



1. Active Tab: Contains all orders in process that have not been received.

In Progress Orders: Orders started but not submitted or sent to the vendor for fulfillment.
 Partially Received Orders: Orders with some

items not received.

•Submitted Orders: Orders sent to the vendor for fulfillment.

2. Received Tab: Contains all orders received.

- 3. Search: Search for an order.
- 4. Cancel: Cancel search
- 5. Order Status Filter: Filter by order status.
- 6. Sort Options
- 7. In Progress Order
- 8. Submitted Order
- 9. Create New Order: Select to start a new order.

Creating a New Order

■ 🕂 Matthews PaintM	lanager® Color Software Beta App: 1	1.8.2003.34 / Data: 1.8.2004.30 Welcome, Sys	Admin Logo	but 3 — 🗂 🗙
System Generated	Create Order			Check box if this is
Number	Order Id	Required Date	Urgent	an urgent order
	200416071817 2	4/16/2020 3 🔁		
	Description	Special Instructions	4	
Select New or	(Optional)	(Optional)		
Existing Vendor	New Vendor Existing Vendor	6		
	First Name	Last Name		
	First name, last name, or company is required	First name, last name, or company is required		
	Company Name	7		
	First name, last name, or company is required	Save	Cancel	

Add Items to the Order

≡ 💠 Matthews PaintManager®	Color Software Beta App: 1.8.2002.25 / D	ata: 1.8.2003.16	Welcome, Sys Ad	Imin Logout (0 _	
< Orders						+ Order
Edit Order					Save	Cancel
ORDER ID	REQUIRED DATE	DESCRIPTION	SPECIAL INSTRUCTIONS	URGENT		
200312072852	3/12/2020					
Existing Contact						
Search existing contacts			8			
Contact Name		Company				
John	Johnson	Johnson Supplies				* •
PRODUCT CODE DESCRIPTION		c	DLOR SYSTEM SKU PACK SIZE UOM	ORDERED 1	Add F	rom Cart
 Add from Add Mir the mini Add Involution Add Sum 	m Cart: Automaticall nimum: Automaticall mum. entory: Manually sel ndry: Manually select	y adds items with "A y adds reorder amou ect items from the Li : items from the Sund	dd to Cart" selection. Ints for all items belo quid Inventory Tab. dries Tab.	2 5 4	Add N Add II Add	Minimum nventory Sundry

Add Items from Suggested Minimums

Reorder Quantity: Reorder quantity entered for this product on the Manage Levels screen.Change Pack Size: Option to change pack size.Delete: Option to remove item from this suggested order.

Add Items from Inventory

Category Filter: Filter the list for easier selection. Filtered Search: List filters as you start typing. Select Products: Select all or select individually. Choose Quantity

Add Items from Sundries

Category Filter: Filter the list for easier selection.Filtered Search: List filters as you start typing.Select Products: Select all or select individually.Choose Quantity

Submit Orders



Receive Orders

Once an order has been submitted it can be received

🔳 💠 Matthe	ews PaintManage	er® Color Software Beta App: 1.8.20	02.25 / Data: 1.8.2003.30			Welcome, Sys Adr	min Logout 🕐) _ 🗆 X		
Corders										
< 200	< 200312072852 : Johnson Supplies-John Johnson 🏻 🖞 🖈									
ORDER ID		REQUIRED DATE	DESCRIPTION	SPECIAL INSTR	UCTIONS	URGENT	STATUS	Edit Order		
200312072852		3/12/2020						Receive Order		
VENDOR		ACCOUNT NUMBER						Necewe Order		
Johnson Supplie	es-John Johnson							Delete Order		
PRODUCT CODE	DESCRIPTION				COLOR SYSTEM	SKU	PACK SIZE UOM			
287113	SUEDE ADDITIVE				Multiple	287113SP/04	1.00 qt	Close Order		
CAN/04	Paint Can, 1 Quart				Paint Lines	CAN/04	1.00 ea	Submit Order		
MAP-LVG951	MEDIUM SILVER				LVG	MAP-LVG951/01	1.00 gal	5.00		
N202	WHITE				Ν	N202SP/01	1.00 gal	8.00		
N930	LIGHT RED				Ν	N930SP/01	1.00 gal	7.00		
N940	RED YELLOW				Ν	N940SP/01	1.00 gal	4.00		
N942	GREEN YELLOW				Ν	N942SP/01	1.00 gal	3.00		

- 1. Tools Menu: Option to receive all products if they were all delivered.
- 2. Receive Individual Items: Individual items can be received.
 - •If all the items on the order are not received, when saved the order will have a status of "Partially Received" and will remain on the Active Tab until all the remaining items are received.

Section 14: Reporting

Program Access Settings for Reports:

Reporting resides inside the *Matthews PaintManager* software and is enabled by navigating from the Dashboard to Settings then Report Settings.

🗮 ⊹ Matthews PaintMa	nager® Color Software B	leta App: 1.8.2002.25)	/ Data: 1.8.2003.16	Welcome, Sys A	idmin Logout 🕜 🔔 🗂 🗙
mp number, name, sour	ce, color family				۵ م
			Settings		
\$	2	77	System Settings	Mixing Settings	User Settings
Settings			Application Settings	Paint Line Settings	Team Management
			Internet Update	★ [#] RFU Paint Line Settings	Report Settings
My Settings	Ready For Use	Reporti	■ ackup and Restore Device Settings Display Settings	★ Ready For Use Preferences	Regional Settings
	Inventory &		Scale Settings		
Jobs	Pricing	l	Print Settings		

From here you can choose the reports to be available for your installation.

Reporting now provides the ability, not only to print, but also to store generated reports. With this new ability, reports can also be scheduled to run automatically.

•Reports are stored in a standard PDF format and can be quickly and easily retrieved when needed.



User Access Settings for Reports

Access to reports can also be configured for an individual user. Navigate to Settings, User Management, and select Edit for a user to configure their report access.

👤 User		11 Presets
Painter	One	Painter* Is Administrator?
User Name Painter1 Password		Jobs Management View Customer List Manage Customer List Manage Teams Modify Closed Jobs
C₂ Language English ▼ United States ▼	党 Expiration Date	Application Settings Manage Users & Settings Software Updates Applications Settings
		Reports Create new reports Create Reports Print and save reports Run Reports Print and save reports View Reports View a report print preview
	Save	Cancel

The Reporting Main Screen

Select Reporting from the Dashboard.



This screen is composed of three main tabs:

- •My Reports Tab: Lists the report templates that store criteria for generating reports.
- •Summary Reports Tab: Contains the summary reports selected in Report Settings.

•Report History Tab: Lists all the generated reports that were saved.



My Reports Tab

- 1. My Report Tab: The default tab when this screen is first selected.
- **2. Filter Options:** Filter by report category and/or report name.
- 3. Saved Reports: All the saved report templates.

Templates contain saved time and data criteria used to generate the report.

- 4. Search Filter: The list will begin to filter as you type.
- 5. Sort Options
- 6. Cancel: Clears all filter, search, and sort selections and restores them to defaults.
- 7. Template Tools Menu
 - Preview a report

•Edit: Change time and data criteria.

•Print

•Delete

8. Create New Report

Summary Reports Tab

Summary reports display a running six month measurement for the selected summary reports.

Keporting				+ Report
My Reports	Summary Rep	orts	Repor	t History
Paint & Materials Gross Profit	Co	st per Refinish Ho	our Sprayables	
\$8,000 \$6,000 \$4,000 \$2,000 \$0 (\$2,000) (\$4,000) Ct-16 Nov-16 Dec-16 Jan	0% \$35 530 10% \$20 20% \$20 30% \$15 510 40% \$5 517 Feb-17 Mar-170% \$8	50.00 \$0.00 tt-16 Nov-16	\$0.00 \$0.00 Dec-16 Jan-17	\$29.79 \$0.00 Feb-17 Mar-17

Report History Tab

This tab stores all reports that have been generated and saved.

- •Automatically groups reports by report category.
- •Each report category is represented by a unique color.
- •System Generated reports are reports that were scheduled to run at a specific time.

Reporting				+ Report
My Reports	Su	immary Reports	Report	Himply
Available Space: 239 GB Used Space 239	5 GB			3 4
All Categories	II Reports	▼ Search Descriptio	in 2	Remove
Refresh From Enter date 5	To Enter dat	e 🖸 Search SORT	6	Date Descending 🔻
	REPORT TYPE	TIME PERIOD	DATE CREATED	CREATOR
▼ COST 7			,	
Repair Order Cost Per Refinish Hour	Repair Order Cost Per	N/A	2/17/2017 9:14 AM	Admin
Shop Cost Per Refinish Hour 8	Shop Cost Per Refinis	2/1/2017 12:00 AM to 2/28/2017 11:59	2/15/2017 1:00 PM	System Generated
Cost by RFU Category and Painter	Cost by RFU Category	2/1/2017 12:00 AM to 2/28/2017 11:59	2/14/2017 9:00 AM	System Generated
▼ GROSS PROFIT				
Gross Profit	Gross Profit	2/1/2017 12:00 AM to 2/28/2017 11:59	2/17/2017 8:59 AM	Admin
Gross Profit By Insurance Company	Gross Profit	2/1/2017 12:00 AM to 2/28/2017 11:59	2/14/2017 9:00 AM	System Generated
		Schedul	ed report	
Waste and Ren Expand or	Waste and Rework	2/1/2017 12:00 AM to 2/28/2017 11:59	2/22/2017 11:00 AM	System Generated
Mix Exception category	Mix Exception	2/1/2017 12:00 AM to 2/28/2017 11:59	2/22/2017 9:00 AM	System Generated

Creating a New Report Template

Select +Report to create a new report template.



Select Report Category and Report



Select Time and Scheduling Options

Not every report will have Time Period selections.

Ex: Sign Order Invoice

Time Period		Parameters
TIME PERIOD 1 Absolute Relative	2 REPORT LENGTH	3
Day Week	 Last Month This Month Next Month 	Time 5:00 AM Day 1 of every 1 month(s)
Month Last Custom		First ✓ Sunday of eve Schedule Start Schedule On 3/2/2017 ⑦ Verification

Time Period

•Relative: Provides standard time period options for quick selection.

•Absolute: When selected disables scheduling and provides to and from date selection.

Report Length

- •Provides standard length periods for quick selection.
- •Used in conjunction with relative time only.

Schedule Report

- •Must be selected to view scheduling options.
- •Available with relative time selection only.
- •When enabled provides recurring scheduling options.

Select Report Parameters

- •Every report will display a unique set of parameters fitting to the objectives of the report.
- •Each new report template will display a unique set of default selections to help get started.
- •Some report templates have a few parameter options and others may have several.



- 1. Pricing: Options to include price, cost, or both.
- 2. Detail and Summary
 - Details

•Summary: Some summaries include graph information.

Both

- 3. Component Inclusion: Component weight selections.
- 4. Weight and Volume: Options for how component UOM are displayed.
- 5. Report Specific: Some reports may have unique parameters tailored to the report objectives.
- 6. Selected Job: Some reports offer options to run for all Jobs or a specific job.
- 7. Selected Painter: Some reports offer the option to run for all users or a specific user.
- 8. Component Volume Unit: Volume unit selections.

Preview & Print Reports

After the template is created you can preview the report to verify the report captures the information you are looking for.

Preview Report



1. Template Save Options

- •Save: Once you have confirmed the template produces the report you need, you can save the template.
- •Save as New: If the report was generated from an existing template you want to keep, you can make changes, preview the report and then save the template with a new name preserving the original one.
- •All saved templates are stored and displayed on the My Reports Tab on the Reports Main screen.

2. Report Save Options

- •Discard and Close: This allows the report to be previewed, possibly printed, but not saved and then return to the Reports Main screen.
- •Save and Close: This allows the report to be previewed, possibly printed, and saved for future retrieval.
- •All saved reports are stored and displayed on the Report History tab on the Report Main screen.
- **3. Print:** Print to the paper printer selected in Settings and Print Settings.

4. View Options

- •Magnify view.
- •Shrink view.
- •Expand report to the edge of the screen.
- •Fit entire report to the screen.

7. Page Navigation

•Advance to end of the report.

•Advance to beginning of the report.

•Advance to the next page.

•Return to the previous page.

6. Refresh: When displaying a report in the office it may be necessary to refresh the report with up-to -date mixing activity.