

# Agilent V3500A Handheld RF Power Meter

**Data Sheet** 



The first palm-sized power meter from Agilent Technologies that delivers high lab quality RF power measurements for installation and maintenance or R&D lab environments

### Why Agilent's Power Meters and Sensors?



### Reliable, high-performing solutions

Every power meter and sensor from Agilent consistently delivers great results.



### A sure investment for many years to come

Code-compatibility between power meters reduces the need for re-coding. Not only that, all Agilent power meters are backward-compatible with most legacy power sensors.



### One specific application: One right solution

Agilent offers a wide selection of power meters and sensors for practically all application needs—wireless communications, radar pulse measurements, component test and more.



### Global network support

No matter where you are, Agilent is committed to giving you the 24-hour support you need regarding our products, applications or services.

Agilent's power meters have long been recognized as the industry standard for RF and microwave power measurements.

### Compact, Portable Solutions for Today's RF Power Measurements

### For production testing



- · Compact build saves rack space
- · Simple set-up and usage
- · Wide dynamic and frequency range

### For R&D and design verification



- · Compact build saves bench space
- · Simple set-up and usage
- · Wide dynamic and frequency range
- · High accuracy
- Advanced troubleshooting of designs with built-in backlight display for easy readings and data recording

### For installation and maintenance



- Integrated power sensor eliminates the need to carry separate sensor
- · Lightweight and rugged
- · Truly portable (with AA batteries)
- Wide dynamic and frequency range
- Quick and easy testing with built-in backlight display

Associated with mobile phones and infrastructure, wireless sensors and transceivers, and WiMAX™, WLAN, RFID, mobile radio, Zigbee, and *Bluetooth*® devices

## Introducing the New Member of the Power Meter Family – the Agilent V3500A

### **Key features**

- Broad 10 MHz to 6 GHz frequency range enables use in variety of applications, including test of mobile phones and infrastructures, WLAN devices, RFID readers, and WiMAX devices
- Large dynamic range of

   63 dBm to +20 dBm
   measures various types of signals, either directly from the device-under-test or through layers of cabling and fixtures
- Integrated power sensor eliminates the need to carry a separate sensor and makes it the most compact and portable RF power measurement instrument
- Internal power reference enables self-calibration and excludes the need to perform independent calibration before using the instrument
- Compensate for cable losses with the Relative Offset function that can add an offset to the display ranging between –99.99 dB and +99.99 dB
- Absolute accuracy up to ±0.21 dB enables more precise characterization of devices, tighter test limits, and more accurate fixture calibration

The Agilent V3500A handheld RF power meter is a compact, portable instrument that makes lab quality RF power measurements in both field and R&D laboratory environments. With an absolute accuracy up to ±0.21 dB, a wide frequency range of 10 MHz to 6 GHz, and measurement range of –63 dBm to +20 dBm, the V3500A is suitable for a wide variety



of RF measurement applications. Its built-in power sensor eliminates the need for users to carry both an instrument and a separate sensor module, and the same sensor is used when duplicating tests or measurements for better repeatability. Truly portable, the V3500A fits easily into your hand or a toolkit and optional loop holster carrying case with shoulder strap is also available to fit your need. To optimize flexibility, it's capable of drawing operating power from batteries, an AC-DC converter module, or a computer via the USB interface. With its features and very attractive price, the V3500A truly redefines superior value.

### High accuracy in both the lab and field

Whether it's used in the field or on the factory floor, the Agilent V3500A makes lab quality RF measurements quickly and easily. Its absolute accuracy up to  $\pm 0.21$  dB,enables more precise characterization of devices, tighter test limits, and more

accurate fixture calibration. In the laboratory, it can be used as an RF power data-logger. Using normal or high speed mode, it easily captures and transfers data to your personal computer through its built-in USB interface (cable supplied), allowing for trend or drift analysis. Despite its small package, the V3500A provides outstanding accuracy on the bench, replacing much larger and more expensive instrumentation.

### Convenient utilities

The V3500A incorporates several handy and practical utilities that make it easier than ever to attain high quality RF measurements with this handheld instrument. Compensate the display reading for any losses or gains between the location where the level of power is desired and the actual point where the power can be measured. Typically the compensation will be required for cable loss. The relative offset factor can be as large as 99.99 dB, and the offset can be programmed with a resolution of 0.01 dB. A number of averaging values can be used when the signal you want to measure varies significantly with time. A hold command saves a measurement that is made in a hard to reach area until the instrument can be retrieved. A backlight can be illuminated when making measurements in poorly lit areas. To maximize battery life, the V3500A can be set up to turn off the backlight or the instrument entirely after a specific period of time. Once the instrument utilities are setup in the manner you prefer, the instrument state can be saved for the next use.



### Take a Closer Look

#### RF connector

In the RF world, cables are often equipped with N-connectors and SMA connectors. N-connectors are commonly used on test instrumentation, because they are rugged, can handle high powers, and perform well up to about 18 GHz.

This section contains information about how to make RF signal connections to the Type N male RF connector (50  $\Omega$  characteristic impedance—refer to Figure 1) of the V3500A for power measurement.

### Connection for a power measurement

**NOTE**: When connecting the Type N connector of the V3500A to a Type N female connector for a power measurement, observe the following proper practice for tightening the connection.

Type N male re connector nut

Agilent V3500A

Handheld RF Power Meter

10 MHz-6 GHz, +20 dBm, 5 VDC Max

ZERO FREQUENCY ON/OFE

BACKLIGHT HOLD

HOLD

Figure 1. Signal connection

While holding the body of the power meter in one hand, turn the Type N male connector nut to tighten the connection (do not turn the body of the V3500A). Continue to do so until the connection is hand-tight. It is important to turn the nut of the connector rather than the body of the power meter when tightening the connection.

### **USB** port

**NOTE:** The term USB (Universal Serial Bus) is used in this data sheet. USB is simply another term for the Universal Serial Bus.

The power meter has a USB 2.0 interface with a USB type Mini-B port (refer to Figure 2). The V3500A can be remotely programmed over this USB interface. In addition to programming, the V3500A can be powered by the USB. With the USB connected and providing power, and the optional external power disconnected, the V3500A will be powered from USB regardless of whether batteries are present.

Body – small and lightweight build to fit into your hand

Built-in backlight display ensures visibility in dark locations

"Zeroing" key function allows a more accurate measurement at low power levels

Frequency keys for rapid setting of input signal

Arrow keys for menu selection and settings

"Hold" key allows saving of measurement that made in hard to reach area until the instrument can be retrieved **NOTE:** The interface is USB 2.0 compatible, but with an interface speed of 12 Mbps.

### External power connector

The power connector provides a connection for the optional external power supply (refer to Figure 2). If the external power supply is connected, the V3500A will be powered by the external supply, regardless of whether USB power or batteries are present.

**CAUTION:** Only connect the optional external power supply (V3500A-PWR) to this connector. Instrument damage may result if improper power is applied.

### Battery power

The V3500A can also be powered by two AA batteries. If installed, the batteries will power the V3500A only if the external power supply and USB are not connected.



USB type Mini-B port for connection to PC

External power connector (use with optional power supply)

Figure 2. USB and power connector

### **Specifications**

The following specifications are based on performance at a temperature of 23 °C  $\pm$  5 °C unless stated otherwise.

| Product specifications                                     |                                                 |                                                                       |                                                   |
|------------------------------------------------------------|-------------------------------------------------|-----------------------------------------------------------------------|---------------------------------------------------|
| Category                                                   | Specifications                                  |                                                                       |                                                   |
| Frequency range                                            | 10 MHz to 6 (                                   | 10 MHz to 6 GHz                                                       |                                                   |
| Power range                                                | -60 dBm to +                                    | -20 dBm                                                               |                                                   |
| Maximum power                                              | +23 dBm, 5 V                                    | /DC                                                                   |                                                   |
| Power accuracy                                             | At 23 °C ±5 °                                   | C1                                                                    | At 0 °C to 50 °C                                  |
| Frequency range<br>10 MHz to 3.75 GHz<br>3.75 GHz to 6 GHz | +20 dBm to -<br>±0.23 dB<br>±0.20 dB            | +6 dBm                                                                | + <b>20 dBm to +6 dBm</b><br>±0.33 dB<br>±0.44 dB |
| Frequency range<br>10 MHz to 3.75 GHz<br>3.75 GHz to 6 GHz | <b>+6 dBm to -9 dBm</b><br>±0.26 dB<br>±0.40 dB |                                                                       | +6 dBm to -9 dBm<br>±0.33 dB<br>±0.55 dB          |
| Frequency range<br>10 MHz to 3.75 GHz<br>3.75 GHz to 6 GHz | <b>−9 dBm to −2</b><br>±0.18 dB<br>±0.19 dB     | 29 dBm                                                                | -10 dBm to -29 dBm<br>±0.29 dB<br>±0.34 dB        |
| Frequency range<br>10 MHz to 3.75 GHz<br>3.75 GHz to 6 GHz | <b>–29 dBm to</b> –<br>±0.22 dB<br>±0.25 dB     | 39 dBm                                                                | <b>–30 dBm to –40 dBm</b><br>±0.32 dB<br>±0.44 dB |
| Frequency range<br>10 MHz to 3.75 GHz<br>3.75 GHz to 6 GHz | <b>−39 dBm to −</b><br>±0.36 dB<br>±0.39 dB     | -50 dBm                                                               | <b>−39 dBm to −50 dBm</b><br>±0.48 dB<br>±0.65 dB |
| Frequency range<br>10 MHz to 3.75 GHz<br>3.75 GHz to 6 GHz | <b>–50 dBm to –</b><br>±1.37 dB<br>±1.81 dB     | -55 dBm                                                               | <b>–50 dBm to –55 dBm</b><br>±1.47 dB<br>±1.97 dB |
| Linearity                                                  | At 23 °C ±5 °                                   | C                                                                     | At 0 °C to 50 °C                                  |
| -40 dBm to +6 dBm                                          | ±0.1 dB                                         |                                                                       | ±0.2 dB                                           |
| -50 dBm to -40 dBm                                         | ±0.4 dB                                         |                                                                       | ±0.5 dB                                           |
| –50 dBm to –55 dBm                                         | ±1.0 dB                                         |                                                                       | ±1.1 dB                                           |
| Noise floor                                                | At 0 °C to 50<br>-61 dBm                        | °C                                                                    |                                                   |
| Speed                                                      | Normal                                          | ~2 readings per second (> $-30$ ~1 readings per second ( $\leq -30$   |                                                   |
|                                                            | High-speed                                      | ~23 readings per second (> $-30$ ~10 readings per second ( $\leq -30$ |                                                   |

1. Customer spec after warm up time of 30 minutes

$$X = (x,f) + K(=2) \cdot \delta(x,f) + \Delta_F(x,f[18\ ^\circ - 28\ ^\circ C]) + \mu$$

where

X is mean of the data taken in the frequency range stated (x,f).

 $\delta$  is standard deviation of the data taken in the frequency range stated (x,f).

x is measured value at test frequencies.

f is frequency range over which data was taken for specification.

μ is measurement uncertainty.


 $\Delta_{\scriptscriptstyle F}$  is change associated temperature variation.

 $18~^{\circ}-28~^{\circ}\text{C}$  is the statistics generated separately at these temperatures and larger statistical value used in setting spec.

### Specifications (continued)

SWR performance for different frequency band

| SWR                                     |                     |  |
|-----------------------------------------|---------------------|--|
| Frequency band                          | SWR (0 °C to 50 °C) |  |
| 10 MHz to 3.75 GHz<br>3.75 GHz to 6 GHz | 1.13<br>1.22        |  |




Typical SWR performance

### Specifications (continued)

| Product characteristics            |                                                                                                                                                                                                                                 |  |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| Power (equipped with auto-shutoff) | <ul> <li>Two 1.5 V alkaline AA batteries (typical battery life: 17.5 hours¹ with low battery indicator</li> <li>USB interface cable (Standard-A to Type-B)²</li> <li>Optional external DC power supply³ (V3500A-PWR)</li> </ul> |  |
| Display                            | <ul> <li>4 digits with backlight and auto-shutoff feature</li> <li>Hold feature—most recent reading is shown on the display and is no longer updated</li> </ul>                                                                 |  |
| Connector                          | <ul> <li>USB 2.0 interface with a mini-B USB connector<sup>4</sup></li> <li>Type N male RF connector (50 Ω characteristic impedance)</li> </ul>                                                                                 |  |
| Operating environment              | <ul> <li>At 0 ° to 50 °C</li> <li>Up to 80% RH for temperature up to 35 °C, non-condensing</li> <li>Altitude up to 2,000 meters</li> </ul>                                                                                      |  |
| Storage compliance                 | <ul> <li>-10 °C to 70 °C</li> <li>Non-operating maximum humidity: 90% at 65 °C, non-condensing</li> </ul>                                                                                                                       |  |
| EMC compliance                     | Certified with  IEC 61326-2-1:2005/EN 61326-2-1:2006  Canada: ICES-001:2004  Australia/New Zealand: AS/NZS CISPR11:2004                                                                                                         |  |
| Pollution degree                   | Pollution Degree 2                                                                                                                                                                                                              |  |
| Dimensions (W × H × D)             | 79 mm × 134 mm × 49 mm (without N-connector)                                                                                                                                                                                    |  |
| Weight                             | 0.5 kg                                                                                                                                                                                                                          |  |
| Waranty                            | <ul> <li>One year for the V3500A Handheld RF Power Meter</li> <li>Three months for the standard shipped and optional accessories</li> </ul>                                                                                     |  |
| Calibration cycle                  | One year                                                                                                                                                                                                                        |  |

- 1. Typical battery life was measured in the default conditions from the factory at 500 MHz with backlight off and no USB communications. With backlight on, typical battery life is 2.5 hours.
- 2. With the USB connected and providing power, and the optional external power disconnected, the V3500A will be powered from USB regardless of whether batteries are present.
- 3. If the external power supply is connected, the V3500A will be powered by the external supply, regardless of whether USB power or batteries are present.
- 4. The interface is USB 2.0 compliant but with an interface speed of 12 Mbps.

### Agilent Power Meter and Power Sensors Selection Guide



### **Ordering Information**



### V3500A handheld RF power meter

### Standard shipped accessories

USB interface cable Type A to Mini-B, 2.5 meter (8.2 feet)



| CD-ROM                                             | Agilent V3500A Product Reference CD-ROM          |  |
|----------------------------------------------------|--------------------------------------------------|--|
| Accessories, calibration and documentation options |                                                  |  |
| V3500A-PWR                                         | External power supply                            |  |
| V3500A-SHL                                         | Holster carry case with shoulder strap           |  |
| V3500A-CA1                                         | USB cable type A to Mini-B, 2.5 meter (8.2 feet) |  |
| V3500A-ABA                                         | English User's Guide                             |  |
| V3500A-0B1                                         | English User's Guide and Installation Guide      |  |
| V3500A-0BW                                         | English Service Guide                            |  |
| V3500A-ABJ                                         | Japanese User's Guide                            |  |
| V3500A-AB2                                         | Simplified Chinese User's Guide                  |  |
|                                                    |                                                  |  |

### www.agilent.com www.agilent.com/find/V3500A



#### www.agilent.com/find/myagilent

A personalized view into the information most relevant to you.



#### www.axiestandard.org

AdvancedTCA® Extensions for Instrumentation and Test (AXIe) is an open standard that extends the AdvancedTCA for general purpose and semiconductor test. Agilent is a founding member of the AXIe consortium.



#### www.lxistandard.org

LAN eXtensions for Instruments puts the power of Ethernet and the Web inside your test systems. Agilent is a founding member of the LXI consortium.



### www.pxisa.org

PCI eXtensions for Instrumentation (PXI) modular instrumentation delivers a rugged, PC-based high-performance measurement and automation system.

### **Agilent Channel Partners**

www.agilent.com/find/channelpartners

Get the best of both worlds: Agilent's measurement expertise and product breadth, combined with channel partner convenience.

Bluetooth and the Bluetooth logos are trademarks owned by Bluetooth SIG, Inc., U.S.A. and licensed to Agilent Technologies, Inc. WiMAX is a trademark of the WiMAX Forum.



### Three-Year Warranty

#### www.agilent.com/find/ThreeYearWarranty

Agilent's combination of product reliability and three-year warranty coverage is another way we help you achieve your business goals: increased confidence in uptime, reduced cost of ownership and greater convenience.



### **Agilent Advantage Services**

www.agilent.com/find/AdvantageServices
Accurate measurements throughout the
life of your instruments.

Aglert Electronic Measurement Group
DEKRA Certified
ISO 9001:2008
Quality Management System

www.agilent.com/quality

For more information on Agilent Technologies' products, applications or services, please contact your local Agilent office. The complete list is available at: www.agilent.com/find/contactus

#### **Americas**

| Canada        | (877) 894 4414 |
|---------------|----------------|
| Brazil        | (11) 4197 3600 |
| Mexico        | 01800 5064 800 |
| United States | (800) 829 4444 |

#### **Asia Pacific**

| Australia          | 1 800 629 485  |
|--------------------|----------------|
| China              | 800 810 0189   |
| Hong Kong          | 800 938 693    |
| India              | 1 800 112 929  |
| Japan              | 0120 (421) 345 |
| Korea              | 080 769 0800   |
| Malaysia           | 1 800 888 848  |
| Singapore          | 1 800 375 8100 |
| Taiwan             | 0800 047 866   |
| Other AP Countries | (65) 375 8100  |

**Europe & Middle East** 

| Belgium        | 32 (0) 2 404 93 40   |
|----------------|----------------------|
| Denmark        | 45 45 80 12 15       |
| Finland        | 358 (0) 10 855 2100  |
| France         | 0825 010 700*        |
|                | *0.125 €/minute      |
| Germany        | 49 (0) 7031 464 6333 |
| Ireland        | 1890 924 204         |
| Israel         | 972-3-9288-504/544   |
| Italy          | 39 02 92 60 8484     |
| Netherlands    | 31 (0) 20 547 2111   |
| Spain          | 34 (91) 631 3300     |
| Sweden         | 0200-88 22 55        |
| United Kingdom | 44 (0) 118 927 6201  |

For other unlisted countries: www.agilent.com/find/contactus (BP-3-1-13)

Product specifications and descriptions in this document subject to change without notice.

© Agilent Technologies, Inc. 2013 Published in USA, April 4, 2013 5990-5483EN

