




WEST RANCHO DOMINGUEZ - 1938



WEST RANCHO DOMINGUEZ - 1941



WEST RANCHO DOMINGUEZ - 1952



WEST RANCHO DOMINGUEZ - 1965



WEST RANCHO DOMINGUEZ - 1976



WEST RANCHO DOMINGUEZ - 1989



WEST RANCHO DOMINGUEZ - 2007




FAIRFAX & SOUTH BALDWIN HILLS – CURRENT SETTING

- Seven plugged wells generally located in line running north to south.
- Site is within a Priority Restoration Area (PRA).
- Site is located within the unincorporated Baldwin Hills area, across existing soccer and baseball fields.
- Wells may need to be re-abandoned to meet current CalGEM standards.



FAIRFAX & SOUTH BALDWIN HILLS - 1927

- Aerial photograph from August 1 1927.
- Scale: 1:18,000
- Oil fields are the predominant land use, followed by agriculture.
- Residential use is minimal.



FAIRFAX & SOUTH BALDWIN HILLS - 1938

- Aerial photograph from May 22 1938.
- Scale: 1:20,000
- Oil fields are the predominant land use, followed by agriculture.
- Expansion of residential use to the southeast.



FAIRFAX & SOUTH BALDWIN HILLS - 1941

- Aerial photograph from December 21 1941.
- Scale: 1:24,000
- Further expansion of residential land use towards the east, south and southeast.
- Oil fields remain active on Site and Site Vicinity (Baldwin Hills)



FAIRFAX & SOUTH BALDWIN HILLS - 1956

- Aerial photograph from August 14 1956.
- Scale: 1:14,400
- Expansion of residential land use towards southwest.
- Oil fields remain active on Site and Site Vicinity (Baldwin Hills)
- Recreation park appears on south end of Site.



FAIRFAX & SOUTH BALDWIN HILLS - 1962

- Aerial photograph from December 15 1962.
- Scale: 1:12,000
- Further expansion of residential land use towards the west.
- Oil fields remain active on most of the Site and Site Vicinity (Baldwin Hills)
- Recreation park expands slightly to the north.




FAIRFAX & SOUTH BALDWIN HILLS - 1971

- Aerial photograph from April 1 1971.
- Scale: 1:12,000
- Expansion of residential land use towards the northeast.
- Oil fields remain active on Site and Site Vicinity (Baldwin Hills)
- A new building with a parking lot appears within the recreation park.




FAIRFAX & SOUTH BALDWIN HILLS - 1989

- Aerial photograph from March 30 1989.
- Scale: 1:31,680
- Expansion of residential and some commercial land use in all directions.
- Oil fields remain active on Site
- Decrease of oil fields in the Site Vicinity.
- New buildings appear within the recreation park.



FAIRFAX & SOUTH BALDWIN HILLS - 2007

- Aerial photograph from February 24, 2007.
- Scale: 1:24,000
- Predominant land use is residential, followed by oil fields and a recreation park.
- Oil fields remain active on Site and to the north of the recreation park.



FAIRFAX & SOUTH BALDWIN HILLS - 1927



FAIRFAX & SOUTH BALDWIN HILLS - 1938



FAIRFAX & SOUTH BALDWIN HILLS - 1941



FAIRFAX & SOUTH BALDWIN HILLS - 1956



FAIRFAX & SOUTH BALDWIN HILLS - 1962



FAIRFAX & SOUTH BALDWIN HILLS - 1971



FAIRFAX & SOUTH BALDWIN HILLS - 1989



FAIRFAX & SOUTH BALDWIN HILLS - 2007



CASTAIC

- Three idle wells, generally located in line running north to south, and one well to the south of the park.
- Site is not within a DAC or Priority Restoration Area.
- Site is located in the unincorporated community of Castaic, just south of the Castaic Sports Complex.



CASTAIC - 1930

- Aerial image taken on July 18, 1930.
- Scale = 1:18,000
- The Site appears to be used for agriculture.
- Site vicinity is largely undeveloped with some agricultural land use.




CASTAIC – 1939

- Aerial image taken on January 1, 1939.
- Scale = 1:4,800
- The Site appears to remain as agricultural.
- Electrical power lines are present.
- Unknown sump-like feature appears along the east side of the property.
- A suspected residence appears directly south of the Site.



CASTAIC - 1952

- Aerial image taken on November 3, 1952.
- Scale = 1:20,000
- The Site appears to remain as agricultural.
- A suspected oil derrick appears on the Southern end of the Site.
- Some expansion of residential and agricultural land use to the northwest of the Site.




CASTAIC - 1966

- Aerial image taken on April 13, 1966.
- Scale = 1:14,400
- The Site appears to remain as agricultural.
- The suspected oil derrick remains on the Southern end of the Site.
- Expansion of the suspected residence directly south of the Site.



CASTAIC - 1973

- Aerial image taken on February 19, 1973.
- Scale = 1:24,000
- The Site appears to remain as agricultural.
- Oil field activities are not obvious on the Site, but suspected industrial buildings are present to the southeast of the Site.
- Suspected residence to the South of Site is no longer present.
- Further expansion of residential land use to the northwest of the Site.




CASTAIC - 1989

- Aerial image taken on May 26, 1989.
- Scale = 1:31,680
- The Site appears vacant with some commercial development in the northwest area.
- Approximately 2 oil wells appear near the southeast area of the Site.
- Further development of industrial buildings to the southeast of the Site.
- Further expansion of residential land use to the northwest of the Site.
- Commercial development to the north of the Site.



CASTAIC - 1994

- Aerial image taken on June 1, 1994.
- Scale = 1:40,000
- The northern area of Site is redeveloped into a recreational park; southern area remains undeveloped.
- Oil field activities are present on the southeast area of the Site.
- Industrial buildings remain present to the southeast of the Site.
- Expansion of residential land use to the west, northwest, and south of the Site.
- Commercial development to the north of the Site.




CASTAIC - 2008

- Aerial image taken on April 14, 2008.
- Scale = 1:25,000
- The northern area of Site remains a recreational park; southern area remains undeveloped
- Oil field activities are present on the southeast area of the Site.
- Industrial buildings remain present to the southeast of the Site.
- A new building appears to the south of the Site,
- Expansion of residential land use to the west, northwest, and south of the Site.


Commercial development to the north of the Site.



CASTAIC - 1930



CASTAIC - 1939



CASTAIC - 1952



CASTAIC - 1966

Agricultural
Fields & Residential

Agricultural
Fields

Undeveloped

Undeveloped

Agricultural
Fields

Undeveloped

I-5 Freeway

Tapia Canyon Rd
Suspected
Residence

CASTAIC - 1973

Residential



Undeveloped

Agricultural
Fields

Undeveloped

I-5 Freeway

Undeveloped

Industrial
Buildings

Tapia Canyon Rd
Former
Residence

CASTAIC - 1989



CASTAIC - 1994



CASTAIC - 1994

