

S800 HDE PK Belting Reduces Wear, Breakage, and Inspection Time

Challenge

- Weekly foreign material (FM) incidents due to broken plastic belt modules
- Delayed startup due to lengthy belt inspections

Solution

Intralox® S800 Open Hinge Flat Top with Heavy-Duty Edge in PK material

Results

- Total elimination of belt-related foreign material incidents
- Minimal wear compared to previous belts
- ~30% reduction in belt inspection time

ZERO

BELT-RELATED FM INCIDENTS
AFTER IMPLEMENTATION

~30%

REDUCTION IN BELT
INSPECTION TIME



“The S800 HDE PK belts show nowhere near as much wear as our previous belts, and the edges still look like they did the day we installed them. We can now breeze through belt inspections rather than checking edge by edge. We’ve replaced multiple belts with PK.”